



15MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 29.JUN.2025 16:17:34

15MHz_Middle_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 29.JUN.2025 16:18:15

15MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 29.JUN.2025 16:18:55

20MHz_Low_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 29.JUN.2025 16:19:42

20MHz_Middle_QPSK_1@0(30MHz~18.55GHz)



ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 29.JUN.2025 16:20:35

20MHz_High_QPSK_1@0(30MHz~18.55GHz)




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 29.JUN.2025 16:21:15


LTE Band 7, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~26.7GHz)




5MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




5MHz_High_QPSK_1@0(30MHz~26.7GHz)




10MHz_Low_QPSK_1@0(30MHz~26.7GHz)




10MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



10MHz_High_QPSK_1@0(30MHz~26.7GHz)




15MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUL.2025 22:01:22

15MHz_Middle_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUL.2025 22:01:43

15MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUL.2025 22:02:04

20MHz_Low_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUL.2025 22:02:28

20MHz_Middle_QPSK_1@0(30MHz~26.7GHz)



ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUL.2025 22:02:48

20MHz_High_QPSK_1@0(30MHz~26.7GHz)




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUL.2025 22:03:09


LTE Band 12, Normal

1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~8.16GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




1.4MHz_High_QPSK_1@0(30MHz~8.16GHz)




3MHz_Low_QPSK_1@0(30MHz~8.16GHz)




3MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




3MHz_High_QPSK_1@0(30MHz~8.16GHz)




5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




5MHz_High_QPSK_1@0(30MHz~8.16GHz)




10MHz_Low_QPSK_1@0(30MHz~8.16GHz)



10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




10MHz_High_QPSK_1@0(30MHz~8.16GHz)




LTE Band 17, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~8.16GHz)




5MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




5MHz_High_QPSK_1@0(30MHz~8.16GHz)




10MHz_Low_QPSK_1@0(30MHz~8.16GHz)



10MHz_Middle_QPSK_1@0(30MHz~8.16GHz)




10MHz_High_QPSK_1@0(30MHz~8.16GHz)




LTE Band 38, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~27.2GHz)




5MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




5MHz_High_QPSK_1@0(30MHz~27.2GHz)




10MHz_Low_QPSK_1@0(30MHz~27.2GHz)




10MHz_Middle_QPSK_1@0(30MHz~27.2GHz)



10MHz_High_QPSK_1@0(30MHz~27.2GHz)




15MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 29.JUN.2025 17:46:26

15MHz_Middle_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 29.JUN.2025 17:47:08

15MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 29.JUN.2025 17:47:50

20MHz_Low_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 29.JUN.2025 17:49:18

20MHz_Middle_QPSK_1@0(30MHz~27.2GHz)



ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 29.JUN.2025 17:50:01

20MHz_High_QPSK_1@0(30MHz~27.2GHz)




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 29.JUN.2025 17:50:45


LTE Band 66, Normal

1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




1.4MHz_High_QPSK_1@0(30MHz~18.8GHz)




3MHz_Low_QPSK_1@0(30MHz~18.8GHz)




3MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




3MHz_High_QPSK_1@0(30MHz~18.8GHz)




5MHz_Low_QPSK_1@0(30MHz~18.8GHz)




5MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




5MHz_High_QPSK_1@0(30MHz~18.8GHz)




10MHz_Low_QPSK_1@0(30MHz~18.8GHz)




10MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



10MHz_High_QPSK_1@0(30MHz~18.8GHz)




15MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUL.2025 22:08:06

15MHz_Middle_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUL.2025 22:08:25

15MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUL.2025 22:08:45

20MHz_Low_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUL.2025 22:09:09

20MHz_Middle_QPSK_1@0(30MHz~18.8GHz)



ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUL.2025 22:09:28

20MHz_High_QPSK_1@0(30MHz~18.8GHz)




ProjectNo.:2502U36006E-RF Tester:Loge Long
Date: 30.JUL.2025 22:09:48


LTE B41_2, Normal

1RB was the worst case


5MHz_Low_QPSK_1@0(30MHz~27.55GHz)




5MHz_Middle_QPSK_1@0(30MHz~27.55GHz)




5MHz_High_QPSK_1@0(30MHz~27.55GHz)




10MHz_Low_QPSK_1@0(30MHz~27.55GHz)




10MHz_Middle_QPSK_1@0(30MHz~27.55GHz)




10MHz_High_QPSK_1@0(30MHz~27.55GHz)




15MHz_Low_QPSK_1@0(30MHz~27.55GHz)




15MHz_Middle_QPSK_1@0(30MHz~27.55GHz)




15MHz_High_QPSK_1@0(30MHz~27.55GHz)




20MHz_Low_QPSK_1@0(30MHz~27.55GHz)



20MHz_Middle_QPSK_1@0(30MHz~27.55GHz)



20MHz_High_QPSK_1@0(30MHz~27.55GHz)



***** END *****