

KO-STAR DEVELOPMENT CO., LTD
No.3, Yicun Industrial Area, Xikeng, Henggang Town, Longgang District
Shenzhen, China

May 22, 2025

Office of Engineering Technology
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046
USA

Subject: Explanation of differences between product types

FCC ID: 2ALHZNB-1096


Models: NB-1096, MZX3050, MZX3050- BLK, MZX3050-WHT, MZX3050-GRY, NB-1096PRO, NB-1092, NB-1093, NB-2040, NB-2046, NB-1700, NB-1600, NB-1701, NB-1100, NB-1090P, NB-1090, NB-1090BNB-1060, NB-1070, NB-1050, NB-1705, NB-1705PV, NB-1300B, BT-1802, BT-1092, BT-2020, BT-1094, BT-1700, BT-1600, BT-1095, BT-1001, BT-1092T, BT-1704, BT-1703, BT-128, BT-1709, BT-1708, BT-1705PV, BT-1705, BT-1500, BT-1094, BT-1100, BT-1090, BT-1070, BT-1070S, BT-1060, T-1702, BT-265, BT-261, BT-685, BT-688, BT-689

To Whom It May Concern:

We, The KO-STAR DEVELOPMENT CO., LTD hereby declare that the model : MZX3050, MZX3050- BLK, MZX3050-WHT, MZX3050- GRY, NB-1096PRO, NB-1092, NB-1093, NB-2040, NB-2046, NB-1700, NB-1600, NB-1701, NB-1100, NB-1090P, NB-1090, NB-1090BNB-1060, NB-1070, NB-1050, NB-1705, NB-1705PV, NB-1300B, BT-1802, BT-1092, BT-2020, BT-1094, BT-1700, BT-1600, BT-1095, BT-1001, BT-1092T, BT-1704, BT-1703, BT-128, BT-1709, BT-1708, BT-1705PV, BT-1705, BT-1500, BT-1094, BT-1100, BT-1090, BT-1070, BT-1070S, BT-1060, T-1702, BT-265, BT-261, BT-685, BT-688, BT-689 is identical with the model : NB-1096, except for the model names.

Sincerely,

KO-STAR DEVELOPMENT CO., LTD
Signature:



[LING YAN, Engineer assitant]