



Band 66_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 5.SEP.2022 12:11:25

Band 66_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 5.SEP.2022 12:11:56

Band 66_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 5.SEP.2022 12:15:24

Band 66_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 5.SEP.2022 12:15:53

Band 66_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 5.SEP.2022 12:16:22

Band 66_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 5.SEP.2022 12:16:44

Band 66_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 5.SEP.2022 12:17:09

Band 66_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 5.SEP.2022 12:17:35

Band 41_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.SEP.2022 19:24:26

Band 41_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 14.SEP.2022 19:24:51

Band 41_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.SEP.2022 19:25:19

Band 41_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 14.SEP.2022 19:25:48

Band 41_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.SEP.2022 19:26:10

Band 41_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 14.SEP.2022 19:26:35

Band 41_5 MHz_High_QPSK_RB25#0_3(26.5GHz-27GHz)




Date: 15.NOV.2022 09:59:47

Band 41_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 14.SEP.2022 19:27:03

Band 41_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 14.SEP.2022 19:27:29

Band 41_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 14.SEP.2022 19:27:51

Band 41_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 14.SEP.2022 19:28:13

Band 41_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 14.SEP.2022 19:28:41

Band 41_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 14.SEP.2022 19:29:07

Band 41_10 MHz_High_QPSK_RB50#0_3(26GHz-27GHz)




Date: 15.NOV.2022 09:59:23

Band 41_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 14.SEP.2022 19:29:38

Band 41_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 14.SEP.2022 19:30:07

Band 41_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 14.SEP.2022 19:30:39

Band 41_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 14.SEP.2022 19:31:07

Band 41_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 14.SEP.2022 19:31:33

Band 41_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 14.SEP.2022 19:31:55

Band 41_15 MHz_High_QPSK_RB75#0_3(26.5GHz-27GHz)




Date: 15.NOV.2022 09:58:53

Band 41_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 14.SEP.2022 19:32:33

Band 41_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 14.SEP.2022 19:32:56

Band 41_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 14.SEP.2022 19:33:28

Band 41_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 14.SEP.2022 19:33:50

Band 41_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 14.SEP.2022 19:34:25

Band 41_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)



Date: 14.SEP.2022 19:34:47

Band 41_20 MHz_High_QPSK_RB100#0_3(26.5GHz-27GHz)



Date: 15.NOV.2022 09:58:25