



5MHz_High_16QAM_1@24




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 15:51:47

5MHz_High_16QAM_25@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 15:52:00

10MHz_Low_QPSK_1@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 15:53:50

10MHz_Low_QPSK_50@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 15:54:03

10MHz_Low_16QAM_1@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 15:54:16

10MHz_Low_16QAM_25@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 15:54:29

10MHz_High_QPSK_1@49




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 15:54:52

10MHz_High_QPSK_50@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 15:55:05

10MHz_High_16QAM_1@49




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 15:55:18

10MHz_High_16QAM_25@25




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 15:55:32

15MHz_Low_QPSK_1@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 15:56:30

15MHz_Low_QPSK_75@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 15:56:43

15MHz_Low_16QAM_1@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 15:56:57

15MHz_Low_16QAM_25@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 15:57:11

15MHz_High_QPSK_1@74




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 15:57:33

15MHz_High_QPSK_75@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 15:57:46

15MHz_High_16QAM_1@74




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 15:58:00

15MHz_High_16QAM_25@50




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 15:58:13

20MHz_Low_QPSK_1@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 15:59:04

20MHz_Low_QPSK_100@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 15:59:17

20MHz_Low_16QAM_1@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 15:59:31

20MHz_Low_16QAM_25@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 15:59:45

20MHz_High_QPSK_1@99




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:00:08

20MHz_High_QPSK_100@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:00:21

20MHz_High_16QAM_1@99



ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:00:34


20MHz_High_16QAM_25@75



ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:00:48


Band 66 , Normal

1.4MHz_Low_QPSK_1@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:01:41

1.4MHz_Low_QPSK_6@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:02:04

1.4MHz_Low_16QAM_1@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:02:27

1.4MHz_Low_16QAM_6@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:02:50

1.4MHz_High_QPSK_1@5




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:03:21

1.4MHz_High_QPSK_6@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:03:44

1.4MHz_High_16QAM_1@5




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:04:07

1.4MHz_High_16QAM_6@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:04:30

3MHz_Low_QPSK_1@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:06:51

3MHz_Low_QPSK_15@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:07:17

3MHz_Low_16QAM_1@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:07:43

3MHz_Low_16QAM_15@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:08:10

3MHz_High_QPSK_1@14




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:08:46

3MHz_High_QPSK_15@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:09:13

3MHz_High_16QAM_1@14




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:09:39

3MHz_High_16QAM_15@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:10:06

5MHz_Low_QPSK_1@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:10:43

5MHz_Low_QPSK_25@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:11:08

5MHz_Low_16QAM_1@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:11:33

5MHz_Low_16QAM_25@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:11:58

5MHz_High_QPSK_1@24




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:12:33

5MHz_High_QPSK_25@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:12:58

5MHz_High_16QAM_1@24




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:13:23

5MHz_High_16QAM_25@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:13:47

10MHz_Low_QPSK_1@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:15:56

10MHz_Low_QPSK_50@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:16:30

10MHz_Low_16QAM_1@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:17:05

10MHz_Low_16QAM_25@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:17:41

10MHz_High_QPSK_1@49




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:18:25

10MHz_High_QPSK_50@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:19:00

10MHz_High_16QAM_1@49




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:19:35

10MHz_High_16QAM_25@25




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:20:11

15MHz_Low_QPSK_1@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:21:08

15MHz_Low_QPSK_75@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:21:52

15MHz_Low_16QAM_1@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:22:37

15MHz_Low_16QAM_25@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:23:21

15MHz_High_QPSK_1@74




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:24:15

15MHz_High_QPSK_75@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:25:00

15MHz_High_16QAM_1@74




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:25:44

15MHz_High_16QAM_25@50




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:26:29

20MHz_Low_QPSK_1@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:29:01

20MHz_Low_QPSK_100@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:29:57

20MHz_Low_16QAM_1@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:30:52

20MHz_Low_16QAM_25@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:31:48

20MHz_High_QPSK_1@99




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:32:53

20MHz_High_QPSK_100@0




ProjectNo.:2502P03369E-RF Tester:Loge Long
 Date: 12.FEB.2025 16:33:48

20MHz_High_16QAM_1@99



ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:34:43

20MHz_High_16QAM_25@75



ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 16:35:38


Spurious Emissions at Antenna Terminal

FCC Part 22H


Band 5 , Normal

1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~9.49GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




1.4MHz_High_QPSK_1@0(30MHz~9.49GHz)




3MHz_Low_QPSK_1@0(30MHz~9.49GHz)




3MHz_Middle_QPSK_1@0(30MHz~9.49GHz)



3MHz_High_QPSK_1@0(30MHz~9.49GHz)




5MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 14:22:08

5MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 14:22:26

5MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 14:22:44

10MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 14:24:13

10MHz_Middle_QPSK_1@0(30MHz~9.49GHz)



ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 14:24:50

10MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 12.FEB.2025 14:25:27


FCC Part 24E

Band 2 , Normal
 1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~20.1GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




1.4MHz_High_QPSK_1@0(30MHz~20.1GHz)




3MHz_Low_QPSK_1@0(30MHz~20.1GHz)




3MHz_Middle_QPSK_1@0(30MHz~20.1GHz)



3MHz_High_QPSK_1@0(30MHz~20.1GHz)




5MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 24.FEB.2025 13:25:53

5MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 24.FEB.2025 13:26:12

5MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 24.FEB.2025 13:26:35

10MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 24.FEB.2025 13:33:34

10MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 24.FEB.2025 13:34:15

10MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 24.FEB.2025 13:34:54

15MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 24.FEB.2025 13:37:19

15MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 24.FEB.2025 13:37:57

15MHz_High_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 24.FEB.2025 13:38:35

20MHz_Low_QPSK_1@0(30MHz~20.1GHz)




ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 24.FEB.2025 13:41:26

20MHz_Middle_QPSK_1@0(30MHz~20.1GHz)



ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 24.FEB.2025 13:42:07

20MHz_High_QPSK_1@0(30MHz~20.1GHz)



ProjectNo.:2502P03369E-RF Tester:Loge Long
Date: 24.FEB.2025 13:42:49