












8.2.7 Conducted RF Spurious Emission



Condition	Mode	Frequency (MHz)	Antenna	Max Value (dBc)	Limit (dBc)	Verdict
NVNT	ax20	2412	Ant1	-51.3	-20	Pass
NVNT	ax20	2412	Ant2	-51.6	-20	Pass
NVNT	ax20	2437	Ant1	-50.48	-20	Pass
NVNT	ax20	2437	Ant2	-49.36	-20	Pass
NVNT	ax20	2462	Ant1	-51.89	-20	Pass
NVNT	ax20	2462	Ant2	-53.42	-20	Pass
NVNT	ax40	2422	Ant1	-47.78	-20	Pass
NVNT	ax40	2422	Ant2	-49.62	-20	Pass
NVNT	ax40	2437	Ant1	-49.31	-20	Pass
NVNT	ax40	2437	Ant2	-50.39	-20	Pass
NVNT	ax40	2452	Ant1	-42.88	-20	Pass
NVNT	ax40	2452	Ant2	-48.79	-20	Pass
NVNT	n20	2412	Ant1	-48.31	-20	Pass
NVNT	n20	2412	Ant2	-50.8	-20	Pass
NVNT	n20	2437	Ant1	-51.2	-20	Pass
NVNT	n20	2437	Ant2	-50.64	-20	Pass
NVNT	n20	2462	Ant1	-45.75	-20	Pass
NVNT	n20	2462	Ant2	-50.18	-20	Pass
NVNT	n40	2422	Ant1	-49.63	-20	Pass
NVNT	n40	2422	Ant2	-49.13	-20	Pass
NVNT	n40	2437	Ant1	-47.76	-20	Pass
NVNT	n40	2437	Ant2	-50.47	-20	Pass
NVNT	n40	2452	Ant1	-47.35	-20	Pass
NVNT	n40	2452	Ant2	-47.49	-20	Pass























































































END OF REPORT