



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 26.OCT.2022 17:10:48

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 26.OCT.2022 17:11:05

Band 2_1.4 MHz_Middle_QPSK_RB6#0




Date: 26.OCT.2022 17:11:26

Band 2_1.4 MHz_Middle_16QAM_RB6#0




Date: 26.OCT.2022 17:11:46

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 26.OCT.2022 17:12:08

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 26.OCT.2022 17:12:25

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 26.OCT.2022 17:12:45

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 26.OCT.2022 17:13:00

Band 2_3 MHz_Middle_QPSK_RB15#0




Date: 26.OCT.2022 17:13:15

Band 2_3 MHz_Middle_16QAM_RB15#0




Date: 26.OCT.2022 17:13:29

Band 2_3 MHz_High_QPSK_RB15#0




Date: 26.OCT.2022 17:13:44

Band 2_3 MHz_High_16QAM_RB15#0




Date: 26.OCT.2022 17:13:58

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 26.OCT.2022 17:14:19

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 26.OCT.2022 17:14:40

Band 2_5 MHz_Middle_QPSK_RB25#0




Date: 26.OCT.2022 17:15:02

Band 2_5 MHz_Middle_16QAM_RB25#0




Date: 26.OCT.2022 17:15:23

Band 2_5 MHz_High_QPSK_RB25#0




Date: 26.OCT.2022 17:15:45

Band 2_5 MHz_High_16QAM_RB25#0




Date: 26.OCT.2022 17:16:09

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 26.OCT.2022 17:16:27

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 26.OCT.2022 17:16:43

Band 2_10 MHz_Middle_QPSK_RB50#0




Date: 26.OCT.2022 17:16:59

Band 2_10 MHz_Middle_16QAM_RB50#0




Date: 26.OCT.2022 17:17:17

Band 2_10 MHz_High_QPSK_RB50#0




Date: 26.OCT.2022 17:17:37

Band 2_10 MHz_High_16QAM_RB50#0




Date: 26.OCT.2022 17:17:52

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 26.OCT.2022 17:18:23

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 26.OCT.2022 17:18:44

Band 2_15 MHz_Middle_QPSK_RB75#0




Date: 26.OCT.2022 17:19:09

Band 2_15 MHz_Middle_16QAM_RB75#0




Date: 26.OCT.2022 17:19:33

Band 2_15 MHz_High_QPSK_RB75#0




Date: 26.OCT.2022 17:19:55

Band 2_15 MHz_High_16QAM_RB75#0




Date: 26.OCT.2022 17:20:19

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 26.OCT.2022 17:20:51

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 26.OCT.2022 17:21:12

Band 2_20 MHz_Middle_QPSK_RB100#0




Date: 26.OCT.2022 17:21:35

Band 2_20 MHz_Middle_16QAM_RB100#0




Date: 26.OCT.2022 17:21:56

Band 2_20 MHz_High_QPSK_RB100#0




Date: 26.OCT.2022 17:22:25

Band 2_20 MHz_High_16QAM_RB100#0




Date: 26.OCT.2022 17:22:49

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 26.OCT.2022 17:23:15

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 26.OCT.2022 17:23:39

Band 4_1.4 MHz_Middle_QPSK_RB6#0




Date: 26.OCT.2022 17:23:57

Band 4_1.4 MHz_Middle_16QAM_RB6#0




Date: 26.OCT.2022 17:24:17

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 26.OCT.2022 17:24:38

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 26.OCT.2022 17:24:56

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 26.OCT.2022 17:25:16

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 26.OCT.2022 17:25:30

Band 4_3 MHz_Middle_QPSK_RB15#0




Date: 26.OCT.2022 17:25:48

Band 4_3 MHz_Middle_16QAM_RB15#0




Date: 26.OCT.2022 17:26:02

Band 4_3 MHz_High_QPSK_RB15#0




Date: 26.OCT.2022 17:26:17

Band 4_3 MHz_High_16QAM_RB15#0




Date: 26.OCT.2022 17:26:32

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 26.OCT.2022 17:26:59

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 26.OCT.2022 17:27:20

Band 4_5 MHz_Middle_QPSK_RB25#0




Date: 26.OCT.2022 17:27:38

Band 4_5 MHz_Middle_16QAM_RB25#0




Date: 26.OCT.2022 17:28:00

Band 4_5 MHz_High_QPSK_RB25#0




Date: 26.OCT.2022 17:28:21

Band 4_5 MHz_High_16QAM_RB25#0




Date: 26.OCT.2022 17:30:31

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 26.OCT.2022 17:30:54

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 26.OCT.2022 17:31:12

Band 4_10 MHz_Middle_QPSK_RB50#0




Date: 26.OCT.2022 17:31:28

Band 4_10 MHz_Middle_16QAM_RB50#0




Date: 26.OCT.2022 17:31:44

Band 4_10 MHz_High_QPSK_RB50#0




Date: 26.OCT.2022 17:32:03

Band 4_10 MHz_High_16QAM_RB50#0




Date: 26.OCT.2022 17:32:22

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 26.OCT.2022 17:32:49

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 26.OCT.2022 17:33:14

Band 4_15 MHz_Middle_QPSK_RB75#0




Date: 26.OCT.2022 17:33:35

Band 4_15 MHz_Middle_16QAM_RB75#0




Date: 26.OCT.2022 17:34:00

Band 4_15 MHz_High_QPSK_RB75#0




Date: 26.OCT.2022 17:34:25

Band 4_15 MHz_High_16QAM_RB75#0




Date: 26.OCT.2022 17:34:49

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 26.OCT.2022 17:35:14

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 26.OCT.2022 17:35:39

Band 4_20 MHz_Middle_QPSK_RB100#0




Date: 26.OCT.2022 17:36:04

Band 4_20 MHz_Middle_16QAM_RB100#0




Date: 26.OCT.2022 17:36:29

Band 4_20 MHz_High_QPSK_RB100#0




Date: 26.OCT.2022 17:36:54

Band 4_20 MHz_High_16QAM_RB100#0




Date: 26.OCT.2022 17:37:19

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 26.OCT.2022 17:37:46

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 26.OCT.2022 17:38:10

Band 7_5 MHz_Middle_QPSK_RB25#0




Date: 26.OCT.2022 17:38:44

Band 7_5 MHz_Middle_16QAM_RB25#0




Date: 26.OCT.2022 17:39:08

Band 7_5 MHz_High_QPSK_RB25#0




Date: 26.OCT.2022 17:39:27

Band 7_5 MHz_High_16QAM_RB25#0




Date: 26.OCT.2022 17:39:48

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 26.OCT.2022 17:40:07

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 26.OCT.2022 17:40:25

Band 7_10 MHz_Middle_QPSK_RB50#0




Date: 26.OCT.2022 17:40:44

Band 7_10 MHz_Middle_16QAM_RB50#0




Date: 26.OCT.2022 17:41:03

Band 7_10 MHz_High_QPSK_RB50#0




Date: 26.OCT.2022 17:41:22

Band 7_10 MHz_High_16QAM_RB50#0




Date: 26.OCT.2022 17:41:41

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 26.OCT.2022 17:42:06

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 26.OCT.2022 17:42:30

Band 7_15 MHz_Middle_QPSK_RB75#0




Date: 26.OCT.2022 17:42:52

Band 7_15 MHz_Middle_16QAM_RB75#0




Date: 26.OCT.2022 17:43:20

Band 7_15 MHz_High_QPSK_RB75#0




Date: 26.OCT.2022 17:43:41

Band 7_15 MHz_High_16QAM_RB75#0




Date: 26.OCT.2022 17:44:06

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 26.OCT.2022 17:44:34

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 26.OCT.2022 17:44:58

Band 7_20 MHz_Middle_QPSK_RB100#0




Date: 26.OCT.2022 17:45:21

Band 7_20 MHz_Middle_16QAM_RB100#0




Date: 26.OCT.2022 17:45:42

Band 7_20 MHz_High_QPSK_RB100#0




Date: 26.OCT.2022 17:46:08

Band 7_20 MHz_High_16QAM_RB100#0




Date: 26.OCT.2022 17:46:29

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 27.OCT.2022 13:07:46

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 27.OCT.2022 13:08:03

Band 5_1.4 MHz_Middle_QPSK_RB6#0




Date: 27.OCT.2022 13:08:21

Band 5_1.4 MHz_Middle_16QAM_RB6#0




Date: 27.OCT.2022 13:08:38

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 27.OCT.2022 13:08:53

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 27.OCT.2022 13:09:10

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 27.OCT.2022 13:09:27

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 27.OCT.2022 13:09:44

Band 5_3 MHz_Middle_QPSK_RB15#0




Date: 27.OCT.2022 13:10:02

Band 5_3 MHz_Middle_16QAM_RB15#0




Date: 27.OCT.2022 13:10:23

Band 5_3 MHz_High_QPSK_RB15#0




Date: 27.OCT.2022 13:10:41

Band 5_3 MHz_High_16QAM_RB15#0




Date: 27.OCT.2022 13:10:55

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 27.OCT.2022 13:11:19

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 27.OCT.2022 13:11:37

Band 5_5 MHz_Middle_QPSK_RB25#0




Date: 27.OCT.2022 13:11:56

Band 5_5 MHz_Middle_16QAM_RB25#0




Date: 27.OCT.2022 13:12:14

Band 5_5 MHz_High_QPSK_RB25#0




Date: 27.OCT.2022 13:12:39

Band 5_5 MHz_High_16QAM_RB25#0




Date: 27.OCT.2022 13:12:56

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 27.OCT.2022 13:13:18

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 27.OCT.2022 13:13:33

Band 5_10 MHz_Middle_QPSK_RB50#0




Date: 27.OCT.2022 13:13:53

Band 5_10 MHz_Middle_16QAM_RB50#0




Date: 27.OCT.2022 13:14:11

Band 5_10 MHz_High_QPSK_RB50#0




Date: 27.OCT.2022 13:14:33

Band 5_10 MHz_High_16QAM_RB50#0




Date: 27.OCT.2022 13:14:52

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 27.OCT.2022 18:38:01

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 27.OCT.2022 18:38:34

Band 38_5 MHz_Middle_QPSK_RB25#0




Date: 27.OCT.2022 18:38:56

Band 38_5 MHz_Middle_16QAM_RB25#0




Date: 27.OCT.2022 18:39:20

Band 38_5 MHz_High_QPSK_RB25#0




Date: 27.OCT.2022 18:39:51

Band 38_5 MHz_High_16QAM_RB25#0




Date: 27.OCT.2022 18:40:22

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 27.OCT.2022 18:40:52

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 27.OCT.2022 18:41:11

Band 38_10 MHz_Middle_QPSK_RB50#0




Date: 27.OCT.2022 18:41:36

Band 38_10 MHz_Middle_16QAM_RB50#0




Date: 27.OCT.2022 18:41:55

Band 38_10 MHz_High_QPSK_RB50#0




Date: 27.OCT.2022 18:42:20

Band 38_10 MHz_High_16QAM_RB50#0




Date: 27.OCT.2022 18:42:45

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 27.OCT.2022 18:43:18

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 27.OCT.2022 18:43:42

Band 38_15 MHz_Middle_QPSK_RB75#0




Date: 27.OCT.2022 18:44:23

Band 38_15 MHz_Middle_16QAM_RB75#0




Date: 27.OCT.2022 18:44:47

Band 38_15 MHz_High_QPSK_RB75#0




Date: 27.OCT.2022 18:45:28

Band 38_15 MHz_High_16QAM_RB75#0




Date: 27.OCT.2022 18:45:52

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 27.OCT.2022 18:46:20

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 27.OCT.2022 18:46:47

Band 38_20 MHz_Middle_QPSK_RB100#0




Date: 27.OCT.2022 18:47:19

Band 38_20 MHz_Middle_16QAM_RB100#0




Date: 27.OCT.2022 18:47:40

Band 38_20 MHz_High_QPSK_RB100#0




Date: 27.OCT.2022 18:48:05

Band 38_20 MHz_High_16QAM_RB100#0




Date: 27.OCT.2022 18:48:27

Band 26_1.4 MHz_Low_QPSK_RB6#0




Date: 4.NOV.2022 17:15:53

Band 26_1.4 MHz_Low_16QAM_RB6#0




Date: 4.NOV.2022 17:16:08

Band 26_1.4 MHz_Middle_QPSK_RB6#0




Date: 4.NOV.2022 17:16:27

Band 26_1.4 MHz_Middle_16QAM_RB6#0




Date: 4.NOV.2022 17:16:48

Band 26_1.4 MHz_High_QPSK_RB6#0




Date: 4.NOV.2022 17:17:06

Band 26_1.4 MHz_High_16QAM_RB6#0




Date: 4.NOV.2022 17:17:24

Band 26_3 MHz_Low_QPSK_RB15#0




Date: 4.NOV.2022 17:17:41

Band 26_3 MHz_Low_16QAM_RB15#0




Date: 4.NOV.2022 17:17:59

Band 26_3 MHz_Middle_QPSK_RB15#0




Date: 4.NOV.2022 17:18:18

Band 26_3 MHz_Middle_16QAM_RB15#0




Date: 4.NOV.2022 17:18:36

Band 26_3 MHz_High_QPSK_RB15#0




Date: 4.NOV.2022 17:18:51

Band 26_3 MHz_High_16QAM_RB15#0




Date: 4.NOV.2022 17:19:06

Band 26_5 MHz_Low_QPSK_RB25#0




Date: 4.NOV.2022 17:19:36

Band 26_5 MHz_Low_16QAM_RB25#0




Date: 4.NOV.2022 17:19:55

Band 26_5 MHz_Middle_QPSK_RB25#0




Date: 4.NOV.2022 17:20:14

Band 26_5 MHz_Middle_16QAM_RB25#0




Date: 4.NOV.2022 17:20:33

Band 26_5 MHz_High_QPSK_RB25#0




Date: 4.NOV.2022 17:20:52

Band 26_5 MHz_High_16QAM_RB25#0




Date: 4.NOV.2022 17:21:11

Band 26_10 MHz_Middle_QPSK_RB50#0




Date: 4.NOV.2022 17:21:32

Band 26_10 MHz_Middle_16QAM_RB50#0




Date: 4.NOV.2022 17:21:52

Band 26_15 MHz_Low_QPSK_RB75#0




Date: 4.NOV.2022 17:01:38

Band 26_15 MHz_Low_16QAM_RB75#0




Date: 4.NOV.2022 17:02:00

Band 26_15 MHz_Middle_QPSK_RB75#0




Date: 4.NOV.2022 17:02:25

Band 26_15 MHz_Middle_16QAM_RB75#0




Date: 4.NOV.2022 17:02:51

Band 26_15 MHz_High_QPSK_RB75#0



Date: 4.NOV.2022 17:03:13

Band 26_15 MHz_High_16QAM_RB75#0



Date: 4.NOV.2022 17:03:35