



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 30.NOV.2021 11:52:03

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 30.NOV.2021 11:52:25

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 30.NOV.2021 11:52:48

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 30.NOV.2021 11:53:17

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 30.NOV.2021 11:53:49

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 30.NOV.2021 11:54:06

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 30.NOV.2021 11:54:36

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 30.NOV.2021 11:55:04

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 30.NOV.2021 11:55:37

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 30.NOV.2021 11:55:59

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 30.NOV.2021 11:56:29

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 30.NOV.2021 11:56:54

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.NOV.2021 11:57:25

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 30.NOV.2021 11:57:47

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.NOV.2021 11:58:19

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 30.NOV.2021 11:58:45

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.NOV.2021 11:59:11

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 30.NOV.2021 11:59:34

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:00:03

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:00:25

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:00:53

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:01:12

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:01:42

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:02:08

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:02:42

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:03:14

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:03:47

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:04:09

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:04:42

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:05:08

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:05:39

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:06:04

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:06:34

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:06:56

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:07:26

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:07:45

Band 4_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:08:13

Band 4_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:08:39

Band 4_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:09:08

Band 4_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:09:37

Band 4_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:10:06

Band 4_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:10:32

Band 4_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:11:06

Band 4_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:11:29

Band 4_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:11:58

Band 4_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:12:24

Band 4_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:12:56

Band 4_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:13:22

Band 4_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:13:50

Band 4_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:14:16

Band 4_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:14:42

Band 4_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:15:07

Band 4_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:15:37

Band 4_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:16:02

Band 4_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:16:41

Band 4_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:17:00

Band 4_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:17:31

Band 4_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:17:56

Band 4_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:18:24

Band 4_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:18:49

Band 4_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:19:27

Band 4_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:19:46

Band 4_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:20:16

Band 4_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:20:42

Band 4_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:21:18

Band 4_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:21:43

Band 4_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:22:20

Band 4_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:22:48

Band 4_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:23:31

Band 4_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:23:56

Band 4_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:24:23

Band 4_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 30.NOV.2021 12:24:48

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:25:18

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 30.NOV.2021 12:25:46

Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:26:16

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 30.NOV.2021 12:26:41

Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:27:17

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 30.NOV.2021 12:27:42

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:28:14

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 30.NOV.2021 12:28:42

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:29:12

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 30.NOV.2021 12:29:34

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:30:00

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 30.NOV.2021 12:30:29

Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:31:00

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 30.NOV.2021 12:31:26

Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:31:52

Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 30.NOV.2021 12:32:14

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.NOV.2021 12:32:40

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 30.NOV.2021 12:33:15

Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.NOV.2021 13:02:35

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 30.NOV.2021 13:03:07

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.NOV.2021 13:03:37

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 30.NOV.2021 13:03:59

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.NOV.2021 13:04:33

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 30.NOV.2021 13:04:58

Band 7_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.NOV.2021 13:05:28

Band 7_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 30.NOV.2021 13:05:51

Band 7_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.NOV.2021 13:06:26

Band 7_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 30.NOV.2021 13:06:46

Band 7_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.NOV.2021 13:07:15

Band 7_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 30.NOV.2021 13:07:37

Band 7_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.NOV.2021 13:08:10

Band 7_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 30.NOV.2021 13:08:38

Band 7_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.NOV.2021 13:09:09

Band 7_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 30.NOV.2021 13:09:34

Band 7_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.NOV.2021 13:10:11

Band 7_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 30.NOV.2021 13:10:40

Band 7_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 30.NOV.2021 13:11:13

Band 7_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 30.NOV.2021 13:11:42

Band 7_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 30.NOV.2021 13:12:18

Band 7_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 30.NOV.2021 13:12:43

Band 7_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 30.NOV.2021 13:13:16

Band 7_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 30.NOV.2021 13:13:42

Band 7_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 30.NOV.2021 13:14:13

Band 7_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 30.NOV.2021 13:14:39

Band 7_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 30.NOV.2021 13:15:12

Band 7_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 30.NOV.2021 13:15:34

Band 7_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 30.NOV.2021 13:16:10

Band 7_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)



Date: 30.NOV.2021 13:16:35