



## Appendix D. SAR Test Setup Photos

### Head Exposure Condition



Front at 10 mm



Bottom Side at 10 mm

### Body-worn Exposure Condition



Front at 0 mm



Back at 0 mm




Right Side at 0 mm




Left Side at 0 mm



Body-worn Exposure Condition



Top Side at 0 mm



Bottom Side at 0 mm



Front with Clip at 0 mm



Extremity Exposure Condition



Front at 0 mm



Back at 0 mm



Right Side at 0 mm



Left Side at 0 mm



Top Side at 0 mm



Bottom Side at 0 mm