



462 Rue des Forges, Trois-Rivières  
Québec, Canada  
G9A 2H5

12/13/2018

Nemko Canada Inc  
303 River Road  
Ottawa  
K1V 1H2  
Canada

**Subject:**

**Bluetooth functionality disabled on TOF RTLS READER  
FCC ID: 2AP77PLURITAG  
IC: 24070-PLURITAG**

**Bluetooth functionality disabled on TOF RTLS ASSET TAG  
FCC ID: 2AP77PLURITAG1  
IC: 24070-PLURITAG1**

Pluritag declares that the Bluetooth functionality of the Decawave DMW1001 module integrated into the TOF RTLS Reader is disabled and is not used.

Pluritag declares that the Bluetooth functionality of the Decawave DMW1001 module integrated into the TOF RTLS ASSET TAG is disabled and is not used.

Pluritag declares that the Bluetooth functionality of the Raspberry PI board integrated into the TOF RTLS Reader is disabled and is not used. Only the WiFi option is enabled on the Raspberry PI board.

Pluritag declares that the Raspberry PI board integrated into the TOF RTLS Reader is accessible by the end-user or field technician and the FCC ID is visible without difficulty when the transmitter is accessed. No modifications or physical changes to the transmitter and housing have been made. The PCB type antenna integrated on the board by the manufacturer is used, and all FCC grant conditions and usage configurations are properly followed.

Signed:

A handwritten signature in black ink, appearing to read "Guillaume Parenteau", written over a horizontal line.

Printed name: Guillaume Parenteau  
Title: CEO  
Date: 12/13/2018  
On behalf of: Pluritag Inc.