



Test setup photographs



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Eclipse Rx
Model: 081778
Test #: 180417
Test to: CFR47 15C
File: 081778 short Term Conf TSup

SN: Eng1
FCC ID: 2APDD081778
Date: May 22, 2018
Page 1 of 5



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Eclipse Rx
Model: 081778
Test #: 180417
Test to: CFR47 15C
File: 081778 short Term Conf TSup

SN: Eng1
FCC ID: 2APDD081778
Date: May 22, 2018
Page 2 of 5



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Eclipse Rx
Model: 081778
Test #: 180417
Test to: CFR47 15C
File: 081778 short Term Conf TSup



SN: Eng1
FCC ID: 2APDD081778
Date: May 22, 2018
Page 3 of 5



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Eclipse Rx
Model: 081778
Test #: 180417
Test to: CFR47 15C
File: 081778 short Term Conf TSup

SN: Eng1
FCC ID: 2APDD081778
Date: May 22, 2018
Page 4 of 5



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Eclipse Rx
Model: 081778
Test #: 180417
Test to: CFR47 15C
File: 081778 short Term Conf TSup

SN: Eng1
FCC ID: 2APDD081778
Date: May 22, 2018
Page 5 of 5