

# BTL Inc.

To: Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046  
USA

**Subject: Request to place FCC ID: 2APRZ-MAXWELL in audit mode and supersede test report exhibit**


To whom it may concern,

We, BTL Inc., are requesting to place FCC ID: 2APRZ-MAXWELL in audit mode. We found that the correct factors of radiated emission below 1 GHz in the DTS/DSS test report exhibits are mis-applied with factory factors instead of new calibrated factors. And we have verified that the test results with the new factors are still in compliance with the requirements of the FCC regulations and updated the test reports.

For RF Exposure report, the FCC Rule Part description is modified to match the accredited description and the calculation facility address is added. The changes do not affect the device's compliance.

If you have any questions regarding this application, please feel free to contact me.

Signature:



Date:

2023-04-06

City:

Taipei

Name:

Alex Pai

Function:

Vice President

Telephone:

+886-2-2641-8198

E-mail:

[alex.pai@newbtl.com](mailto:alex.pai@newbtl.com)