


FCC ID: 2APRZ-MAXWELL DTS test report modification cross comparison chart

FCC ID	2APRZ-MAXWELL	
Equipment Class	DTS	
Radio Function	BLE	
Report No.	BTL-FCCP-2-2209T130	
Modified Page Number	1, 5, 32, 33; Total 4 pages.	
Modified	Original	Note
 Report No.: BTL-FCCP-2-2209T130 <h3>FCC Radio Test Report</h3> <p>FCC ID: 2APRZ-MAXWELL</p> <p>Report No. : BTL-FCCP-2-2209T130 Equipment : Maxwell headset Model Name : Maxwell Brand Name : Audeze LLC Applicant : Audeze LLC Address : 3410 S Susan St, Santa Ana, CA 92704 USA</p> <p>Radio Function : Bluetooth Low Energy</p> <p>FCC Rule Part(s) : FCC CFR Title 47, Part 15, Subpart C (15.247) Measurement Procedure(s) : ANSI C63.10-2013</p> <p>Date of Receipt : 2022/10/4 Date of Test : 2022/10/4~ 2023/1/17 Issued Date : 2023/3/24</p> <p>The above equipment has been tested and found in compliance with the requirement of the above standards by BTL Inc.</p> <p>Prepared by : <u>Eric Lee</u> Eric Lee, Engineer</p> <p>Approved by : <u>Jerry Chang</u> Jerry Chang, Supervisor</p> <p>BTL Inc. No.18, Ln. 171, Sec. 2, Jiuzong Rd., Neihu Dist., Taipei City 114, Taiwan Tel: +886-2-2657-3299 Fax: +886-2-2657-3331 Web: www.newbtl.com Service mail: btl_qa@newbtl.com</p> <p>Project No.: 2209T130 Page 1 of 61 Report Version: R01</p>	 Report No.: BTL-FCCP-2-2209T130 <h3>FCC Radio Test Report</h3> <p>FCC ID: 2APRZ-MAXWELL</p> <p>Report No. : BTL-FCCP-2-2209T130 Equipment : Maxwell headset Model Name : Maxwell Brand Name : Audeze LLC Applicant : Audeze LLC Address : 3410 S Susan St, Santa Ana, CA 92704 USA</p> <p>Radio Function : Bluetooth Low Energy</p> <p>FCC Rule Part(s) : FCC CFR Title 47, Part 15, Subpart C (15.247) Measurement Procedure(s) : ANSI C63.10-2013</p> <p>Date of Receipt : 2022/10/4 Date of Test : 2022/10/4~ 2022/11/9 Issued Date : 2022/11/30</p> <p>The above equipment has been tested and found in compliance with the requirement of the above standards by BTL Inc.</p> <p>Prepared by : <u>Eric Lee</u> Eric Lee, Engineer</p> <p>Approved by : <u>Jerry Chang</u> Jerry Chang, Supervisor</p> <p>BTL Inc. No.18, Ln. 171, Sec. 2, Jiuzong Rd., Neihu Dist., Taipei City 114, Taiwan Tel: +886-2-2657-3299 Fax: +886-2-2657-3331 Web: www.newbtl.com Service mail: btl_qa@newbtl.com</p> <p>Project No.: 2209T130 Page 1 of 61 Report Version: R00</p>	<p>On page 1, the Date of Test and Issued Date are updated, and the Report Version is updated to R01 on every page due this modification.</p>



FCC ID: 2APRZ-MAXWELL DTS test report modification cross comparison chart

FCC ID	2APRZ-MAXWELL																																	
Equipment Class	DTS																																	
Radio Function	BLE																																	
Report No.	BTL-FCCP-2-2209T130																																	
Modified Page Number	1, 5, 32, 33; Total 4 pages.																																	
Modified	Original			Note																														
 Report No.: BTL-FCCP-2-2209T130 <div style="border: 1px solid #ccc; padding: 10px; margin-top: 10px;"> <p>REVISION HISTORY</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Report No.</th><th>Version</th><th>Description</th><th>Issued Date</th><th>Note</th></tr> </thead> <tbody> <tr> <td>BTL-FCCP-2-2209T130</td><td>R00</td><td>Original Report.</td><td>2022/11/30</td><td>Invalid</td></tr> <tr> <td>BTL-FCCP-2-2209T130</td><td>R01</td><td>Revised report to address TAF Audit's comments.</td><td>2023/3/24</td><td>Valid</td></tr> </tbody> </table> </div> <p>Project No.: 2209T130 Page 5 of 61 Report Version: R01</p>	Report No.	Version	Description	Issued Date	Note	BTL-FCCP-2-2209T130	R00	Original Report.	2022/11/30	Invalid	BTL-FCCP-2-2209T130	R01	Revised report to address TAF Audit's comments.	2023/3/24	Valid	 Report No.: BTL-FCCP-2-2209T130 <div style="border: 1px solid #ccc; padding: 10px; margin-top: 10px;"> <p>REVISION HISTORY</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Report No.</th><th>Version</th><th>Description</th><th>Issued Date</th><th>Note</th></tr> </thead> <tbody> <tr> <td>BTL-FCCP-2-2209T130</td><td>R00</td><td>Original Report.</td><td>2022/11/30</td><td>Valid</td></tr> <tr> <td colspan="5" style="height: 100px;"></td></tr> </tbody> </table> </div> <p>Project No.: 2209T130 Page 5 of 61 Report Version: R00</p>			Report No.	Version	Description	Issued Date	Note	BTL-FCCP-2-2209T130	R00	Original Report.	2022/11/30	Valid						On page 5, in the Report REVISION HISTORY , a Version R01 description is added due to this modification.
Report No.	Version	Description	Issued Date	Note																														
BTL-FCCP-2-2209T130	R00	Original Report.	2022/11/30	Invalid																														
BTL-FCCP-2-2209T130	R01	Revised report to address TAF Audit's comments.	2023/3/24	Valid																														
Report No.	Version	Description	Issued Date	Note																														
BTL-FCCP-2-2209T130	R00	Original Report.	2022/11/30	Valid																														

FCC ID: 2APRZ-MAXWELL DTS test report modification cross comparison chart

FCC ID	2APRZ-MAXWELL																																																																																			
Equipment Class	DTS																																																																																			
Radio Function	BLE																																																																																			
Report No.	BTL-FCCP-2-2209T130																																																																																			
Modified Page Number	1, 5, 32, 33; Total 4 pages.																																																																																			
Modified  Report No.: BTL-FCCP-2-2209T130 <table border="1"> <tr> <td>Test Mode</td> <td>BLE 5.0 (1 Mbps)</td> <td>Test Date</td> <td>2023/1/17</td> </tr> <tr> <td>Test Frequency</td> <td>2480MHz</td> <td>Polarization</td> <td>Vertical</td> </tr> <tr> <td>Temp</td> <td>23°C</td> <td>Hum.</td> <td>59%</td> </tr> </table>  <table border="1"> <thead> <tr> <th>No.</th> <th>Mk.</th> <th>Freq.</th> <th>Reading Level</th> <th>Correct Factor</th> <th>Measure-ment</th> <th>Limit</th> <th>Over</th> </tr> <tr> <th></th> <th></th> <th>MHz</th> <th>dBuV</th> <th>dB</th> <th>dBuV/m</th> <th>dB</th> <th>Detector</th> <th>Comment</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>!</td> <td>52.7303</td> <td>46.28</td> <td>-11.37</td> <td>34.91</td> <td>40.00</td> <td>-5.09</td> <td>peak</td> </tr> <tr> <td>2</td> <td></td> <td>180.9643</td> <td>44.69</td> <td>-13.51</td> <td>31.18</td> <td>43.50</td> <td>-12.32</td> <td>peak</td> </tr> <tr> <td>3</td> <td></td> <td>351.3933</td> <td>45.28</td> <td>-10.32</td> <td>34.96</td> <td>46.00</td> <td>-11.04</td> <td>peak</td> </tr> <tr> <td>4</td> <td></td> <td>463.4607</td> <td>40.01</td> <td>-7.16</td> <td>32.85</td> <td>46.00</td> <td>-13.15</td> <td>peak</td> </tr> <tr> <td>5</td> <td></td> <td>533.2037</td> <td>42.48</td> <td>-5.91</td> <td>36.57</td> <td>46.00</td> <td>-9.43</td> <td>peak</td> </tr> <tr> <td>6</td> <td>*</td> <td>711.4897</td> <td>44.14</td> <td>-2.57</td> <td>41.57</td> <td>46.00</td> <td>-4.43</td> <td>peak</td> </tr> </tbody> </table> <p>REMARKS: (1) Measurement Value = Reading Level + Correct Factor. (2) Margin Level = Measurement Value - Limit Value.</p>		Test Mode	BLE 5.0 (1 Mbps)	Test Date	2023/1/17	Test Frequency	2480MHz	Polarization	Vertical	Temp	23°C	Hum.	59%	No.	Mk.	Freq.	Reading Level	Correct Factor	Measure-ment	Limit	Over			MHz	dBuV	dB	dBuV/m	dB	Detector	Comment	1	!	52.7303	46.28	-11.37	34.91	40.00	-5.09	peak	2		180.9643	44.69	-13.51	31.18	43.50	-12.32	peak	3		351.3933	45.28	-10.32	34.96	46.00	-11.04	peak	4		463.4607	40.01	-7.16	32.85	46.00	-13.15	peak	5		533.2037	42.48	-5.91	36.57	46.00	-9.43	peak	6	*	711.4897	44.14	-2.57	41.57	46.00	-4.43	peak
Test Mode	BLE 5.0 (1 Mbps)	Test Date	2023/1/17																																																																																	
Test Frequency	2480MHz	Polarization	Vertical																																																																																	
Temp	23°C	Hum.	59%																																																																																	
No.	Mk.	Freq.	Reading Level	Correct Factor	Measure-ment	Limit	Over																																																																													
		MHz	dBuV	dB	dBuV/m	dB	Detector	Comment																																																																												
1	!	52.7303	46.28	-11.37	34.91	40.00	-5.09	peak																																																																												
2		180.9643	44.69	-13.51	31.18	43.50	-12.32	peak																																																																												
3		351.3933	45.28	-10.32	34.96	46.00	-11.04	peak																																																																												
4		463.4607	40.01	-7.16	32.85	46.00	-13.15	peak																																																																												
5		533.2037	42.48	-5.91	36.57	46.00	-9.43	peak																																																																												
6	*	711.4897	44.14	-2.57	41.57	46.00	-4.43	peak																																																																												
 Report No.: BTL-FCCP-2-2209T130 <table border="1"> <tr> <td>Test Mode</td> <td>BLE 5.0 (1 Mbps)</td> <td>Test Date</td> <td>2022/10/25</td> </tr> <tr> <td>Test Frequency</td> <td>2480MHz</td> <td>Polarization</td> <td>Vertical</td> </tr> <tr> <td>Temp</td> <td>23°C</td> <td>Hum.</td> <td>59%</td> </tr> </table>  <table border="1"> <thead> <tr> <th>No.</th> <th>Mk.</th> <th>Freq.</th> <th>Reading Level</th> <th>Correct Factor</th> <th>Measure-ment</th> <th>Limit</th> <th>Over</th> </tr> <tr> <th></th> <th></th> <th>MHz</th> <th>dBuV</th> <th>dB</th> <th>dBuV/m</th> <th>dB</th> <th>Detector</th> <th>Comment</th> </tr> </thead> <tbody> <tr> <td>1</td> <td></td> <td>52.7303</td> <td>46.28</td> <td>-18.04</td> <td>28.24</td> <td>40.00</td> <td>-11.76</td> <td>peak</td> </tr> <tr> <td>2</td> <td></td> <td>180.9643</td> <td>44.69</td> <td>-20.07</td> <td>24.62</td> <td>43.50</td> <td>-18.88</td> <td>peak</td> </tr> <tr> <td>3</td> <td></td> <td>351.3933</td> <td>45.28</td> <td>-16.98</td> <td>28.30</td> <td>46.00</td> <td>-17.70</td> <td>peak</td> </tr> <tr> <td>4</td> <td></td> <td>463.4607</td> <td>40.01</td> <td>-14.08</td> <td>25.93</td> <td>46.00</td> <td>-20.07</td> <td>peak</td> </tr> <tr> <td>5</td> <td></td> <td>533.2037</td> <td>42.48</td> <td>-12.57</td> <td>29.91</td> <td>46.00</td> <td>-16.09</td> <td>peak</td> </tr> <tr> <td>6</td> <td>*</td> <td>711.4897</td> <td>44.14</td> <td>-8.86</td> <td>35.28</td> <td>46.00</td> <td>-10.72</td> <td>peak</td> </tr> </tbody> </table> <p>REMARKS: (1) Measurement Value = Reading Level + Correct Factor. (2) Margin Level = Measurement Value - Limit Value.</p>		Test Mode	BLE 5.0 (1 Mbps)	Test Date	2022/10/25	Test Frequency	2480MHz	Polarization	Vertical	Temp	23°C	Hum.	59%	No.	Mk.	Freq.	Reading Level	Correct Factor	Measure-ment	Limit	Over			MHz	dBuV	dB	dBuV/m	dB	Detector	Comment	1		52.7303	46.28	-18.04	28.24	40.00	-11.76	peak	2		180.9643	44.69	-20.07	24.62	43.50	-18.88	peak	3		351.3933	45.28	-16.98	28.30	46.00	-17.70	peak	4		463.4607	40.01	-14.08	25.93	46.00	-20.07	peak	5		533.2037	42.48	-12.57	29.91	46.00	-16.09	peak	6	*	711.4897	44.14	-8.86	35.28	46.00	-10.72	peak
Test Mode	BLE 5.0 (1 Mbps)	Test Date	2022/10/25																																																																																	
Test Frequency	2480MHz	Polarization	Vertical																																																																																	
Temp	23°C	Hum.	59%																																																																																	
No.	Mk.	Freq.	Reading Level	Correct Factor	Measure-ment	Limit	Over																																																																													
		MHz	dBuV	dB	dBuV/m	dB	Detector	Comment																																																																												
1		52.7303	46.28	-18.04	28.24	40.00	-11.76	peak																																																																												
2		180.9643	44.69	-20.07	24.62	43.50	-18.88	peak																																																																												
3		351.3933	45.28	-16.98	28.30	46.00	-17.70	peak																																																																												
4		463.4607	40.01	-14.08	25.93	46.00	-20.07	peak																																																																												
5		533.2037	42.48	-12.57	29.91	46.00	-16.09	peak																																																																												
6	*	711.4897	44.14	-8.86	35.28	46.00	-10.72	peak																																																																												

FCC ID: 2APRZ-MAXWELL DTS test report modification cross comparison chart

FCC ID	2APRZ-MAXWELL									
Equipment Class	DTS									
Radio Function	BLE									
Report No.	BTL-FCCP-2-2209T130									
Modified Page Number	1, 5, 32, 33; Total 4 pages.									
Modified			Original					Note		
 Report No.: BTL-FCCP-2-2209T130			 Report No.: BTL-FCCP-2-2209T130					On page 33, the test result is replaced with new test result which is applied with amended correct factors.		
										
REMARKS: (1) Measurement Value = Reading Level + Correct Factor. (2) Margin Level = Measurement Value - Limit Value.			REMARKS: (1) Measurement Value = Reading Level + Correct Factor. (2) Margin Level = Measurement Value - Limit Value.							
Project No.: 2209T130			Project No.: 2209T130					Report Version: R01		
Page 33 of 61			Page 33 of 61					Report Version: R00		