



Band 4_20 MHz_Low_QPSK_RB100#0




Date: 19.JUN.2022 15:59:40

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 19.JUN.2022 16:00:12

Band 4_20 MHz_Middle_QPSK_RB100#0




Date: 19.JUN.2022 16:00:59

Band 4_20 MHz_Middle_16QAM_RB100#0




Date: 19.JUN.2022 16:01:35

Band 4_20 MHz_High_QPSK_RB100#0




Date: 19.JUN.2022 16:02:21

Band 4_20 MHz_High_16QAM_RB100#0




Date: 19.JUN.2022 16:02:57

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 19.JUN.2022 16:03:27

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 19.JUN.2022 16:03:58

Band 7_5 MHz_Middle_QPSK_RB25#0




Date: 19.JUN.2022 16:04:25

Band 7_5 MHz_Middle_16QAM_RB25#0




Date: 19.JUN.2022 16:04:52

Band 7_5 MHz_High_QPSK_RB25#0




Date: 19.JUN.2022 16:05:13

Band 7_5 MHz_High_16QAM_RB25#0




Date: 19.JUN.2022 16:05:43

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 19.JUN.2022 16:06:20

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 19.JUN.2022 16:06:55

Band 7_10 MHz_Middle_QPSK_RB50#0




Date: 19.JUN.2022 16:07:21

Band 7_10 MHz_Middle_16QAM_RB50#0




Date: 19.JUN.2022 16:08:02

Band 7_10 MHz_High_QPSK_RB50#0




Date: 19.JUN.2022 16:08:36

Band 7_10 MHz_High_16QAM_RB50#0




Date: 19.JUN.2022 16:09:11

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 19.JUN.2022 16:10:10

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 19.JUN.2022 16:10:42

Band 7_15 MHz_Middle_QPSK_RB75#0




Date: 19.JUN.2022 16:11:08

Band 7_15 MHz_Middle_16QAM_RB75#0




Date: 19.JUN.2022 16:11:41

Band 7_15 MHz_High_QPSK_RB75#0




Date: 19.JUN.2022 16:12:21

Band 7_15 MHz_High_16QAM_RB75#0




Date: 19.JUN.2022 16:12:56

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 19.JUN.2022 16:13:33

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 19.JUN.2022 16:14:02

Band 7_20 MHz_Middle_QPSK_RB100#0




Date: 19.JUN.2022 16:14:47

Band 7_20 MHz_Middle_16QAM_RB100#0




Date: 19.JUN.2022 16:15:34

Band 7_20 MHz_High_QPSK_RB100#0




Date: 19.JUN.2022 16:16:16

Band 7_20 MHz_High_16QAM_RB100#0




Date: 19.JUN.2022 16:16:42

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 19.JUN.2022 16:17:23

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 19.JUN.2022 16:17:53

Band 12_1.4 MHz_Middle_QPSK_RB6#0




Date: 19.JUN.2022 16:18:30

Band 12_1.4 MHz_Middle_16QAM_RB6#0




Date: 19.JUN.2022 16:19:17

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 19.JUN.2022 16:19:53

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 19.JUN.2022 16:20:28

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 19.JUN.2022 16:20:49

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 19.JUN.2022 16:21:10

Band 12_3 MHz_Middle_QPSK_RB15#0




Date: 19.JUN.2022 16:21:29

Band 12_3 MHz_Middle_16QAM_RB15#0




Date: 19.JUN.2022 16:21:50

Band 12_3 MHz_High_QPSK_RB15#0




Date: 19.JUN.2022 16:22:14

Band 12_3 MHz_High_16QAM_RB15#0




Date: 19.JUN.2022 16:22:35

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 19.JUN.2022 16:22:58

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 19.JUN.2022 16:23:29

Band 12_5 MHz_Middle_QPSK_RB25#0




Date: 19.JUN.2022 16:23:53

Band 12_5 MHz_Middle_16QAM_RB25#0




Date: 19.JUN.2022 16:24:27

Band 12_5 MHz_High_QPSK_RB25#0




Date: 19.JUN.2022 16:24:47

Band 12_5 MHz_High_16QAM_RB25#0




Date: 19.JUN.2022 16:25:15

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 19.JUN.2022 16:25:42

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 19.JUN.2022 16:26:17

Band 12_10 MHz_Middle_QPSK_RB50#0




Date: 19.JUN.2022 16:26:46

Band 12_10 MHz_Middle_16QAM_RB50#0




Date: 19.JUN.2022 16:27:21

Band 12_10 MHz_High_QPSK_RB50#0




Date: 19.JUN.2022 16:27:53

Band 12_10 MHz_High_16QAM_RB50#0




Date: 19.JUN.2022 16:28:27

Band 17_5 MHz_Low_QPSK_RB25#0




Date: 19.JUN.2022 16:28:48

Band 17_5 MHz_Low_16QAM_RB25#0




Date: 19.JUN.2022 16:29:12

Band 17_5 MHz_Middle_QPSK_RB25#0




Date: 19.JUN.2022 16:29:42

Band 17_5 MHz_Middle_16QAM_RB25#0




Date: 19.JUN.2022 16:30:13

Band 17_5 MHz_High_QPSK_RB25#0




Date: 19.JUN.2022 16:30:37

Band 17_5 MHz_High_16QAM_RB25#0




Date: 19.JUN.2022 16:31:01

Band 17_10 MHz_Low_QPSK_RB50#0




Date: 19.JUN.2022 16:31:28

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 19.JUN.2022 16:32:09

Band 17_10 MHz_Middle_QPSK_RB50#0




Date: 19.JUN.2022 16:32:42

Band 17_10 MHz_Middle_16QAM_RB50#0




Date: 19.JUN.2022 16:33:15

Band 17_10 MHz_High_QPSK_RB50#0



Date: 19.JUN.2022 16:33:53

Band 17_10 MHz_High_16QAM_RB50#0



Date: 19.JUN.2022 16:34:20