



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 19.JUN.2022 18:00:40

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 19.JUN.2022 18:01:05

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 19.JUN.2022 18:01:47

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 19.JUN.2022 18:02:07

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 19.JUN.2022 18:03:00

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 19.JUN.2022 18:03:19

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 19.JUN.2022 18:03:51

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 19.JUN.2022 18:04:17

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 19.JUN.2022 18:04:55

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 19.JUN.2022 18:05:21

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 19.JUN.2022 18:05:53

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 19.JUN.2022 18:06:12

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 19.JUN.2022 18:06:44

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 19.JUN.2022 18:07:03

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 19.JUN.2022 18:07:41

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 19.JUN.2022 18:08:04

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 19.JUN.2022 18:08:42

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 19.JUN.2022 18:09:08

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 19.JUN.2022 18:09:51

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 19.JUN.2022 18:10:16

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 19.JUN.2022 18:10:51

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 19.JUN.2022 18:11:17

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 19.JUN.2022 18:11:45

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 19.JUN.2022 18:12:08

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 19.JUN.2022 18:12:42

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 19.JUN.2022 18:13:01

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 19.JUN.2022 18:13:36

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 19.JUN.2022 18:14:01

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 19.JUN.2022 18:14:46

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 19.JUN.2022 18:15:08

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 19.JUN.2022 18:15:47

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 19.JUN.2022 18:16:10

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 19.JUN.2022 18:16:47

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 19.JUN.2022 18:17:16

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 19.JUN.2022 18:17:50

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 19.JUN.2022 18:18:18

Band 4_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:31:31

Band 4_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 19.JUN.2022 19:31:53

Band 4_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:33:29

Band 4_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 19.JUN.2022 19:33:51

Band 4_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:34:23

Band 4_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 19.JUN.2022 19:34:49

Band 4_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:35:25

Band 4_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 19.JUN.2022 19:35:53

Band 4_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:36:31

Band 4_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 19.JUN.2022 19:36:54

Band 4_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:37:35

Band 4_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 19.JUN.2022 19:37:57

Band 4_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:38:36

Band 4_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 19.JUN.2022 19:38:56

Band 4_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:39:30

Band 4_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 19.JUN.2022 19:39:56

Band 4_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:40:38

Band 4_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 19.JUN.2022 19:41:06

Band 4_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:41:50

Band 4_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 19.JUN.2022 19:42:12

Band 4_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:42:41

Band 4_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 19.JUN.2022 19:43:03

Band 4_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:43:44

Band 4_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 19.JUN.2022 19:44:09

Band 4_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:44:46

Band 4_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 19.JUN.2022 19:45:06

Band 4_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:45:48

Band 4_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 19.JUN.2022 19:46:13

Band 4_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:46:52

Band 4_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 19.JUN.2022 19:47:21

Band 4_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:47:52

Band 4_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 19.JUN.2022 19:48:14

Band 4_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:48:52

Band 4_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 19.JUN.2022 19:49:17

Band 4_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:50:01

Band 4_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 19.JUN.2022 19:50:23

Band 7_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:51:04

Band 7_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 19.JUN.2022 19:51:29

Band 7_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:52:01

Band 7_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 19.JUN.2022 19:52:20

Band 7_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:52:56

Band 7_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 19.JUN.2022 19:53:18

Band 7_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:53:55

Band 7_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 19.JUN.2022 19:54:20

Band 7_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:54:52

Band 7_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 19.JUN.2022 19:55:15

Band 7_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:55:45

Band 7_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 19.JUN.2022 19:56:08

Band 7_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:56:44

Band 7_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 19.JUN.2022 19:57:09

Band 7_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:57:42

Band 7_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 19.JUN.2022 19:58:11

Band 7_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 19.JUN.2022 19:59:04

Band 7_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 19.JUN.2022 19:59:29

Band 7_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 19.JUN.2022 20:00:13

Band 7_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 19.JUN.2022 20:00:38

Band 7_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 19.JUN.2022 20:01:17

Band 7_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 19.JUN.2022 20:01:39

Band 7_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 19.JUN.2022 20:02:15

Band 7_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 19.JUN.2022 20:02:38

Band 12_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 19.JUN.2022 20:03:07

Band 12_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 19.JUN.2022 20:03:29

Band 12_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 19.JUN.2022 20:04:12

Band 12_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 19.JUN.2022 20:04:34

Band 12_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 19.JUN.2022 20:05:13

Band 12_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 19.JUN.2022 20:05:41

Band 12_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 19.JUN.2022 20:06:10

Band 12_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 19.JUN.2022 20:06:39

Band 12_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 19.JUN.2022 20:07:21

Band 12_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 19.JUN.2022 20:07:40

Band 12_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 19.JUN.2022 20:08:17

Band 12_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 19.JUN.2022 20:08:39

Band 12_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 19.JUN.2022 20:09:15

Band 12_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 19.JUN.2022 20:09:41

Band 12_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 19.JUN.2022 20:10:15

Band 12_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 19.JUN.2022 20:10:40

Band 12_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 19.JUN.2022 20:11:12

Band 12_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 19.JUN.2022 20:11:47

Band 12_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 19.JUN.2022 20:12:22

Band 12_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 19.JUN.2022 20:12:45

Band 12_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 19.JUN.2022 20:13:17

Band 12_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 19.JUN.2022 20:13:45

Band 12_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 19.JUN.2022 20:14:24

Band 12_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 19.JUN.2022 20:14:49

Band 17_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 19.JUN.2022 20:15:29

Band 17_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 19.JUN.2022 20:15:57

Band 17_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 19.JUN.2022 20:16:37

Band 17_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 19.JUN.2022 20:16:56

Band 17_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 19.JUN.2022 20:17:34

Band 17_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 19.JUN.2022 20:18:00

Band 17_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 19.JUN.2022 20:18:35

Band 17_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 19.JUN.2022 20:19:00

Band 17_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 19.JUN.2022 20:19:35

Band 17_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 19.JUN.2022 20:20:07

Band 17_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)



Date: 19.JUN.2022 20:20:45

Band 17_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)



Date: 19.JUN.2022 20:21:11