

Date: Sep 11, 2018

Timco Engineering, Inc.
849 N.W. State Road 45
P.O. Box 370
Newberry, Florida 32669 USA

Attestation Letter

We hereby confirm that the product :

FCC ID: 2AQM8-UNITRACERW

have BLE(Bluetooth Low Energy) module, but it is not working
because they do not have any drivers to control it.

Confirmed by,
Name/Title : Yong Kweon JEONG / Manager
Company name : UNISEM Co., Ltd.
Tel : +82-31-8060-0259
E-mail : ykjeong@unisem.co.kr



Yong Kweon JEONG
HW Engineer