



## **Appendix II**

### **Setup Photographs**



## RADIATED RF MEASUREMENT SETUP(WCDMA B5) (ABOVE 1 GHz)






MEASUREMENT POSITION OF WCDMA Band 5 (Y axis)



MEASUREMENT POSITION OF WCDMA Band 5 (Z axis)





MEASUREMENT POSITION OF LORA (X axis)



MEASUREMENT POSITION OF LORA (Y axis)








MEASUREMENT POSITION OF LORA (Z axis)






## RADIATED RF MEASUREMENT SETUP (30MHz~1GHz)

MEASUREMENT POSITION OF WCDMA Band5




MEASUREMENT POSITION OF LORA






## POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP



## RADIATED RF MEASUREMENT SETUP (Below 30MHz)







MEASUREMENT POSITION OF WCDMA Band5

