



HeatWatch

Find it. Fix it. Go Beyond.

WWW.HEATWATCHLIVE.COM


818 6th Avenue, Suite 4N, New York, NY 10001 | Tel: (646) 891-0519

11/16/18

To Whom it May Concern:

This letter is to serve as notice that the sensor “ V5.0”, with FCC ID “2AQX2-HWSEN915” is completely inside the enclosure which is secured and installed during the manufacturing process. This antenna will not be accessible by consumers and does not require any additional adjustments during setup.

Sincerely,



Jeffrey Carleton
President