




Quick Start Guide / 入门指南




Realmax-Qian can bring you to an AR world where you can enjoy the immersive mixture of virtuality and reality. It provides you a new perspective to view the world, think about the world, and better understand the world.

Realmax-乾带你进入AR世界, 让你畅游在虚拟和现实完美结合的梦幻世界中。它让你从新的角度重新观察这个世界, 在新的维度重新思考这个世界, 增强你对真实的现实世界的认识。





Accessories



- | | |
|---------------------------|-------------------------|
| Lithium Battery*1 | Power Adaptor*1 |
| Realmax Qian AR Headset*1 | USB-C Power Cable*1 |
| Portable Package*1 | Micro USB Power Cable*1 |
| Paper Box*1 | Cleaning Cloth*1 |
| VR Cover*1 | Quick Start Guide*1 |
| Controller*1 | |




Basic Operation

Realmax Qian power on and off

Realmax Qian Power On—Press and hold the power button until the power-on LOGO appears on the screen.


Realmax Qian Power Off—Press and hold the power button until the screen displays the power-off image. Follow the prompts to complete the power-off.



Controller power on and off


Controller Power On—Press on the power button for 3 seconds, and see the indicator light flashes.

Controller Power Off—Press on the power button for 8 seconds, see the indicator light flashes 3 times, and then release the button .






Wearing Method





Adjust straps on both sides to fit your head circumference.






Strap Adjustment



Adjust the position of hook on the loop to fit the head.



Switch Method




Put VR cover close to the lens and it will be magnetically attached.




Battery Installation and Disassembly


【Installation】



1 . Firstly, insert the hole under the charging port end into the battery compartment socket.




2 . Secondly, center the socket point and move the other end of the battery down until the battery completely enters the battery compartment.




3 . When you heard a snapping sound, the battery is in place.

【Battery Disassembly】





buckle



Move the toggle switch at the buckle and simultaneously pull the battery up until the battery and battery compartment are completely separated.



Charging



【Attentions】

1. Children's usage of the product must be supervised by adults. Please pay attention to the experience duration.
2. If you have eye diseases or abnormal interpupillary distance, please consult a professional ophthalmologist before using the product.
3. If you feel uncomfortable after wearing the product, stop using the product.
4. Please use the product in indoor environment and outdoor environment without precipitation. Please avoid using this product in extreme environment.
5. This product is not a substitute for a safety helmet. Do not use this product while driving.
6. Please use this product in a safe environment.
7. To avoid losses, do not throw, strike, squeeze or disassemble the product.
8. Long-term usage of this product can cause visual fatigue. Please arrange your using time wisely.
9. Avoid touching lens with your hand. If the lens are stained, please wipe it off with a cloth. DO NOT USE organic solvents to clean the lens.
10. Do not use the product in an environment exceeding 45°C.
11. The battery can only be replaced with a battery of the same type or equivalent type. The battery should not be exposed to excessive heat such as sunlight or fire, to avoid explosion.

【Disclaimer】

Realmax Qian is an AR standalone. No matter you intend to purchase this product in any channel, you should read these terms carefully. Your purchase will be deemed to be an endorsement of this statement.

1. Realmax guarantees the product sold has: reliable quality, true parameters, accurate quantity and can be transported safely.
2. The company is not responsible for any damage caused by improper use or disassembly.
3. The company is not responsible for personal injury or property loss caused by improper use.

【Product Warranty】

Warranty lasts for 12 months since the purchase date (lens coating, straps and lens abrasion are not included.). The warranty is only for the quality of the product itself. It does not include product quality problems caused by human factors, natural disasters and other factors.

【Limitation of Liability】

In any case, the loss that Realmax bears associated with the cost of use or the cost of the product (whether direct or indirect, special, punitive, incidental or other lost profits, business loss, and any economic loss) , must not exceed the price of the product.

【Certification】

The product has obtained Radio Transmission Equipment Type Approval and CCC certification. For the CMIIT ID, please check the nameplate.

FCC Statement

This device complies with Part 15 of the FCC Rules.

Operation is subject to the following two conditions:

(1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules.

These limits are designed to provide reasonable protection against harmful interference in a residential installation.

This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications.

However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

RF Exposure compliance

The Radiated energy from the antenna conforms to the FCC limit of the SAR(specific absorption rate) requirement regarding 47 CFR Part 2 section 1093

NOTE: Any changes or modifications not expressly approved by the grantee of this device could void the user's authority to operate the equipment.





Responsible Party

Realmax USA company name and address, telephone.





包装配件




- | | |
|----------------|-------------------|
| 锂电池*1 | 电源适配器*1 |
| Realmax乾AR眼镜*1 | USB Type C充电数据线*1 |
| 便携包*1 | Micro USB充电线*1 |
| 外包纸盒*1 | 擦镜布*1 |
| VR遮光片*1 | 快速使用向导*1 |
| 手柄*1 | |



基础操作


Realmax乾如何开关机

长按下电源按键直到画面出现开机LOGO, 松开电源按键, 完成开机;
长按下电源按键直到画面出现关机画面, 根据提示完成关机。




手柄如何开关机

手柄打开——按下电源按键3秒, 指示灯闪烁;
手柄关闭——按下电源键8秒直到指示灯连续闪烁3次, 松开按键, 完成关机。






佩戴方法





双手轻拉设备两侧绑带, 绑带柔韧舒适, 可以根据头部自动贴合。






绑带调节



两侧绑带可以根据自身头型大小调节, 轻便舒适。



AR切换方法




将VR遮光片靠近设备镜面前，会自动吸附在上面，完成切换。




电池安装 / 拆卸


【电池安装】



1. 先将电池充电口端下方的空穴插入电池仓套接处。





2. 以电池下方套接处为圆心, 向下移动电池另一端, 直到电池整个进入电池仓。



3. 听到清脆的“喀”声, 说明电池安装到位。



【电池拆卸】



一只手指按住卡扣处的拨动开关, 同时另一手指从卡扣上方的凹槽处向上扣动电池, 直到电池和电池仓完全分离。



充电方法



【注意事项】

1. 儿童体验需在家长或者成年人陪护下进行,同时注意控制体验时间。
2. 如果您有眼疾或者异常瞳距但又需要使用本产品,建议您咨询专业的眼科医生。
3. 如果您佩戴后感觉眼部不适,请停止使用本产品。
4. 请在室内以及没有降水的室外环境下使用本产品,请不要在室外雨雪天气下使用本产品。
5. 本产品不可替代安全头盔,请勿在驾驶汽车、摩托车等情况下使用本产品。
6. 请在安全的环境中使用本产品。
7. 请不要投掷、敲打、挤压、拆卸本产品,以免给您或者产品本身带来损失。
8. 长时间使用本产品会产生视觉疲劳,我们建议您合理安排产品及休息时间。
9. 请尽量避免用手触碰镜片。如果不慎沾上污渍,可以使用眼镜布擦拭干净。切忌使用有机溶剂清洗镜片。
10. 不得在超过45°的环境中使用本产品。
11. 电池只能使用同样类型或者等效类型的电池来更换,不得暴露在诸如日照、火烤等过热环境中,以免爆炸。

【免责条款】

乾是一款AR一体机产品,无论您打算在任何渠道购买本产品,均应该仔细阅读本条款,您的购买行为将被视为对本声明表示认可。

1. Realmax保证所售产品:质量可靠,参数真实、数量准确以及运输安全。
2. 对于因使用不当或者拆卸本产品而造成的损失,本公司概不负责。
3. 任何不遵守注意事项中规定的不正确使用而带来的人身、财产损失,本公司不负责。

【产品保修】

自购买起12个月内保修(不含贴膜、头戴和镜片磨损)。保修仅针对产品本身的质量问题。不包括人为因素、自然灾害等因素造成的产品质量问题。

【责任范围】

在任何情况下,realmax承担的与使用成本或与本品相关的任何损失(无论世界的或者间接的、特殊的、惩罚性的、偶然的或其他损失的利润、亏损业务,以及任何经济损失),不得超过本品售价。

【认证标志】

本产品已取得无线电发射设备型号核准证和CCC认证,CMIIT ID见产品铭牌。

注意:如果电池更换不当会有爆炸危险,只能用同样类型或等效类型的电池来更换,电池(电池包或组合电池)不得暴露在诸如日照、火烤或类似过热环境中的警告。

联系我们 Contact Us

塔普翊海(上海)智能科技有限公司


Tapuyihai (Shanghai) Intelligent Technology Co., Ltd.

Web : www.realmax.com

Email : qian@realmax.com

地址：中国上海市黄浦区中山南路1218号2层

Address : 2/F, No.1218 South Zhongshan Road, Huangpu
District, Shanghai, China



307001017530



关注RealMax黑科技

Scan the code to follow
Realmax Black Technology
on Wechat