



October 17, 2017

Federal Communications Commission  
Authorization & Evaluation Division  
7345 Oakland Mills Road  
Columbia, Maryland 21046

**Subject: Change in Identification**

To Whom It May Concern:

This change in Identification request applies for a new FCC ID, as established in 47CFR 2.933(b) for a currently approved device. This application by Sandia Research Corporation will establish a new FCC ID: 2ARE6-1000 under Sandia Research Corporation's Grantee Code for purpose of marketing. The original grant to Codan Limited will remain in effect.

Per 2.933(b)

1. The original identification is FCC ID: DYY2110
2. The original grant date is 03-08-2005
3. The equipment is electrically identical. Only the trade name and FCC ID are different
4. The original test results are applicable and representative of this changed device
5. External photographs are included in the application

The following files are electronically submitted as attachments:

- Cover letter
- External photos
- FCC ID label & label location

Please contact me if there is any information you may need.

Sincerely,

A handwritten signature in black ink that reads "Paul R. Jorgenson". The signature is fluid and cursive, with the first letters of the first and last names being capitalized and prominent.

Paul R. Jorgenson  
Sandia Research Corporation  
7565 East Eagle Crest Drive  
Suite 101  
Mesa, AZ 85207