



15MHz_High_QPSK_1@74




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:20:49

15MHz_High_QPSK_75@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:21:33

15MHz_High_16QAM_1@74




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:22:16

15MHz_High_16QAM_75@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:23:00

20MHz_Low_QPSK_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:24:11

20MHz_Low_QPSK_100@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:25:05

20MHz_Low_16QAM_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:26:00

20MHz_Low_16QAM_100@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:26:56

20MHz_High_QPSK_1@99




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:28:00

20MHz_High_QPSK_100@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:28:55

20MHz_High_16QAM_1@99



ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:29:50

20MHz_High_16QAM_100@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:30:45

FCC Part 27 & IC RSS 139


B4, Normal

1.4MHz_Low_QPSK_1@0




ProjectNo.:2402Z68759E-RF Testers:Loge Long
Date: 12.DEC.2024 14:31:40

1.4MHz_Low_QPSK_6@0




ProjectNo.:2402Z68759E-RF Testers:Loge Long
Date: 12.DEC.2024 14:32:02

1.4MHz_Low_16QAM_1@0




ProjectNo.:2402Z68759E-RF Testers:Loge Long
Date: 12.DEC.2024 14:32:25

1.4MHz_Low_16QAM_6@0




ProjectNo.:2402Z68759E-RF Testers:Loge Long
Date: 12.DEC.2024 14:32:48

1.4MHz_High_QPSK_1@5




ProjectNo.:2402Z68759E-RF Testers:Loge Long
Date: 12.DEC.2024 14:33:19

1.4MHz_High_QPSK_6@0




ProjectNo.:2402Z68759E-RF Testers:Loge Long
Date: 12.DEC.2024 14:33:41

1.4MHz_High_16QAM_1@5




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:34:04

1.4MHz_High_16QAM_6@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:34:27

3MHz_Low_QPSK_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:35:05

3MHz_Low_QPSK_15@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:35:31

3MHz_Low_16QAM_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:35:57

3MHz_Low_16QAM_15@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:36:23

3MHz_High_QPSK_1@14




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:36:58

3MHz_High_QPSK_15@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:38:19

3MHz_High_16QAM_1@14




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:38:46

3MHz_High_16QAM_15@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:39:13

5MHz_Low_QPSK_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:39:54

5MHz_Low_QPSK_25@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:40:19

5MHz_Low_16QAM_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:40:44

5MHz_Low_16QAM_25@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:41:10

5MHz_High_QPSK_1@24




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:41:46

5MHz_High_QPSK_25@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:42:11

5MHz_High_16QAM_1@24




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:42:35

5MHz_High_16QAM_25@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:42:59

10MHz_Low_QPSK_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:43:49

10MHz_Low_QPSK_50@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:44:24

10MHz_Low_16QAM_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:45:00

10MHz_Low_16QAM_50@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:45:36

10MHz_High_QPSK_1@49




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:46:20

10MHz_High_QPSK_50@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:46:55

10MHz_High_16QAM_1@49




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:47:131

10MHz_High_16QAM_50@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:48:06

15MHz_Low_QPSK_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:49:105

15MHz_Low_QPSK_75@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:49:149

15MHz_Low_16QAM_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:50:133

15MHz_Low_16QAM_75@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 12.DEC.2024 14:51:17

15MHz_High_QPSK_1@74




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:25:46

15MHz_High_QPSK_75@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:27:17

15MHz_High_16QAM_1@74




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:28:01

15MHz_High_16QAM_75@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:28:44

20MHz_Low_QPSK_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:29:51

20MHz_Low_QPSK_100@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:30:45

20MHz_Low_16QAM_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:31:40

20MHz_Low_16QAM_100@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:32:35

20MHz_High_QPSK_1@99




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:33:39

20MHz_High_QPSK_100@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:34:35

20MHz_High_16QAM_1@99



ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:35:30

20MHz_High_16QAM_100@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:36:24


FCC Part 27 & IC RSS 130

B12, Normal


1.4MHz_Low_QPSK_1@0




1.4MHz_Low_QPSK_6@0




1.4MHz_Low_16QAM_1@0




1.4MHz_Low_16QAM_6@0




1.4MHz_High_QPSK_1@5



1.4MHz_High_QPSK_6@0




1.4MHz_High_16QAM_1@5




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 12:44:04

1.4MHz_High_16QAM_6@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 12:44:43

3MHz_Low_QPSK_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 12:45:16

3MHz_Low_QPSK_15@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 12:46:19

3MHz_Low_16QAM_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 12:47:02

3MHz_Low_16QAM_15@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 12:47:46

3MHz_High_QPSK_1@14




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 22:32:32

3MHz_High_QPSK_15@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 12:49:15

3MHz_High_16QAM_1@14




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 12:49:56

3MHz_High_16QAM_15@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 12:50:37

5MHz_Low_QPSK_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 12:51:33

5MHz_Low_QPSK_25@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 12:52:19

5MHz_Low_16QAM_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 12:53:06

5MHz_Low_16QAM_25@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 12:53:52

5MHz_High_QPSK_1@24




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 12:54:43

5MHz_High_QPSK_25@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 12:55:30

5MHz_High_16QAM_1@24




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 12:56:16

5MHz_High_16QAM_25@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 12:57:02

10MHz_Low_QPSK_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 12:58:10

10MHz_Low_QPSK_50@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 12:59:08

10MHz_Low_16QAM_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 13:00:06

10MHz_Low_16QAM_50@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 13:01:04

10MHz_High_QPSK_1@49




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 13:02:10

10MHz_High_QPSK_50@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 13:03:07

10MHz_High_16QAM_1@49



ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 13:04:05

10MHz_High_16QAM_50@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 13:05:09

FCC Part 27 & IC RSS 130


B17, Normal

5MHz_Low_QPSK_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 11:12:57

5MHz_Low_QPSK_25@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 11:13:58

5MHz_Low_16QAM_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 11:14:59

5MHz_Low_16QAM_25@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 11:16:02

5MHz_High_QPSK_1@24




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 11:17:16

5MHz_High_QPSK_25@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 11:18:18

5MHz_High_16QAM_1@24




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 11:19:21

5MHz_High_16QAM_25@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 22:34:38

10MHz_Low_QPSK_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 13:53:17

10MHz_Low_QPSK_50@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 13:54:15

10MHz_Low_16QAM_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 13:55:13

10MHz_Low_16QAM_50@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 13:56:11

10MHz_High_QPSK_1@49




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 13:57:14

10MHz_High_QPSK_50@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 13:58:11

10MHz_High_16QAM_1@49



ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 13:59:08

10MHz_High_16QAM_50@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 28.NOV.2024 14:01:02

FCC Part 27 & IC RSS 139


B66, Normal

1.4MHz_Low_QPSK_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:46:13

1.4MHz_Low_QPSK_6@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:46:53

1.4MHz_Low_16QAM_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:47:17

1.4MHz_Low_16QAM_6@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:47:40

1.4MHz_High_QPSK_1@5




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:48:12

1.4MHz_High_QPSK_6@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:48:36

1.4MHz_High_16QAM_1@5




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:48:59

1.4MHz_High_16QAM_6@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:49:22

3MHz_Low_QPSK_1@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:50:02

3MHz_Low_QPSK_15@0




ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:50:29

3MHz_Low_16QAM_1@0



ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:50:55

3MHz_Low_16QAM_15@0



ProjectNo.:2402Z68759E-RF Tester:Loge Long
Date: 10.DEC.2024 15:51:20