



10MHz_High_16QAM_1@49



ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 22:54:42


10MHz_High_16QAM_50@0



ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 22:55:53


FCC Part 27 & IC RSS 139
LTE Band 66, Normal

1.4MHz_Low_QPSK_1@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 22:56:56

1.4MHz_Low_QPSK_6@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 22:57:38

1.4MHz_Low_16QAM_1@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 22:58:20

1.4MHz_Low_16QAM_6@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 22:59:02

1.4MHz_High_QPSK_1@5




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 22:59:44

1.4MHz_High_QPSK_6@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:00:26

1.4MHz_High_16QAM_1@5




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:01:07

1.4MHz_High_16QAM_6@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:01:54

3MHz_Low_QPSK_1@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:03:12

3MHz_Low_QPSK_15@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:04:03

3MHz_Low_16QAM_1@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:04:53

3MHz_Low_16QAM_15@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:05:44

3MHz_High_QPSK_1@14




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:06:35

3MHz_High_QPSK_15@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:07:26

3MHz_High_16QAM_1@14




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:08:17

3MHz_High_16QAM_15@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:09:10


5MHz_Low_QPSK_1@0




5MHz_Low_QPSK_25@0




5MHz_Low_16QAM_1@0




5MHz_Low_16QAM_25@0




5MHz_High_QPSK_1@24




5MHz_High_QPSK_25@0




5MHz_High_16QAM_1@24




5MHz_High_16QAM_25@0




10MHz_Low_QPSK_1@0




10MHz_Low_QPSK_50@0




10MHz_Low_16QAM_1@0



10MHz_Low_16QAM_50@0




10MHz_High_QPSK_1@49




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:21:21

10MHz_High_QPSK_50@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:22:16

10MHz_High_16QAM_1@49




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:23:11

10MHz_High_16QAM_50@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:24:08

15MHz_Low_QPSK_1@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:25:45

15MHz_Low_QPSK_75@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:26:51

15MHz_Low_16QAM_1@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:27:56

15MHz_Low_16QAM_75@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:28:58

15MHz_High_QPSK_1@74




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:30:01

15MHz_High_QPSK_75@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:31:05

15MHz_High_16QAM_1@74




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:32:09

15MHz_High_16QAM_75@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:33:13

20MHz_Low_QPSK_1@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:35:02

20MHz_Low_QPSK_100@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:36:18

20MHz_Low_16QAM_1@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:37:35

20MHz_Low_16QAM_100@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:38:52

20MHz_High_QPSK_1@99




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:40:09

20MHz_High_QPSK_100@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:41:26

20MHz_High_16QAM_1@99



ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:42:41

20MHz_High_16QAM_100@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 18.JUL.2025 23:43:57


FCC Part 27N & IC RSS 130

LTE Band 71, Normal


5MHz_Low_QPSK_1@0




5MHz_Low_QPSK_25@0




5MHz_Low_16QAM_1@0




5MHz_Low_16QAM_25@0




5MHz_High_QPSK_1@24



5MHz_High_QPSK_25@0




5MHz_High_16QAM_1@24




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 16:34:45

5MHz_High_16QAM_25@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 16:35:33

10MHz_Low_QPSK_1@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 16:37:04

10MHz_Low_QPSK_50@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 16:38:01

10MHz_Low_16QAM_1@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 16:38:58

10MHz_Low_16QAM_50@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 16:39:54

10MHz_High_QPSK_1@49




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 16:40:55

10MHz_High_QPSK_50@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 16:41:55

10MHz_High_16QAM_1@49




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 16:42:55

10MHz_High_16QAM_50@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 16:43:55

15MHz_Low_QPSK_1@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 16:45:39

15MHz_Low_QPSK_75@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 16:46:49

15MHz_Low_16QAM_1@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 17:14:11

15MHz_Low_16QAM_75@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 16:50:15

15MHz_High_QPSK_1@74




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 17:15:24

15MHz_High_QPSK_75@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 17:25:17

15MHz_High_16QAM_1@74




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 16:54:33

15MHz_High_16QAM_75@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 16:55:44

20MHz_Low_QPSK_1@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 17:04:31

20MHz_Low_QPSK_100@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 17:27:09

20MHz_Low_16QAM_1@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 17:28:31

20MHz_Low_16QAM_100@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 17:33:07

20MHz_High_QPSK_1@99




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 17:34:31

20MHz_High_QPSK_100@0




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 17:35:52

20MHz_High_16QAM_1@99



ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 18:17:52

20MHz_High_16QAM_100@0



ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 19.JUL.2025 18:14:02


Spurious Emissions at Antenna Terminal

Note: For all bands except LTE Band 7, the maximum offset setting is applied to configure Conducted Spurious Emissions testing.

FCC Part 22H & IC RSS 132


LTE Band 5, Normal
1RB was the worst case

1.4MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 21.JUL.2025 19:22:21

1.4MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 21.JUL.2025 19:22:37

1.4MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 21.JUL.2025 19:22:53

3MHz_Low_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 21.JUL.2025 19:24:12

3MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 21.JUL.2025 19:24:30

3MHz_High_QPSK_1@0(30MHz~9.49GHz)




ProjectNo.:2502V28134E-RF Tester:Loge Long
Date: 21.JUL.2025 19:24:47


5MHz_Low_QPSK_1@0(30MHz~9.49GHz)




5MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




5MHz_High_QPSK_1@0(30MHz~9.49GHz)




10MHz_Low_QPSK_1@0(30MHz~9.49GHz)



10MHz_Middle_QPSK_1@0(30MHz~9.49GHz)




10MHz_High_QPSK_1@0(30MHz~9.49GHz)




FCC Part 24E & IC RSS 133

LTE Band 2, Normal
1RB was the worst case


1.4MHz_Low_QPSK_1@0(30MHz~20.1GHz)




1.4MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




1.4MHz_High_QPSK_1@0(30MHz~20.1GHz)




3MHz_Low_QPSK_1@0(30MHz~20.1GHz)




3MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




3MHz_High_QPSK_1@0(30MHz~20.1GHz)




5MHz_Low_QPSK_1@0(30MHz~20.1GHz)




5MHz_Middle_QPSK_1@0(30MHz~20.1GHz)




5MHz_High_QPSK_1@0(30MHz~20.1GHz)



10MHz_Low_QPSK_1@0(30MHz~20.1GHz)



10MHz_Middle_QPSK_1@0(30MHz~20.1GHz)



10MHz_High_QPSK_1@0(30MHz~20.1GHz)

