



10MHz\_Low\_QPSK\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 08:55:41

10MHz\_Low\_QPSK\_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 08:56:15

10MHz\_Low\_16QAM\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 08:56:50

10MHz\_Low\_16QAM\_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 08:57:24

10MHz\_High\_QPSK\_1@49




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 08:58:05

10MHz\_High\_QPSK\_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 08:58:39

10MHz\_High\_16QAM\_1@49




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 08:59:14

10MHz\_High\_16QAM\_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 08:59:48

15MHz\_Low\_QPSK\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 09:00:42

15MHz\_Low\_QPSK\_75@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 09:01:25

15MHz\_Low\_16QAM\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 09:02:08

15MHz\_Low\_16QAM\_75@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 09:02:52

15MHz\_High\_QPSK\_1@74




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 09:45:53

15MHz\_High\_QPSK\_75@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 09:42:24

15MHz\_High\_16QAM\_1@74




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 09:43:08

15MHz\_High\_16QAM\_75@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 09:43:52

20MHz\_Low\_QPSK\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 09:46:59

20MHz\_Low\_QPSK\_100@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 09:47:54

20MHz\_Low\_16QAM\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 09:48:49

20MHz\_Low\_16QAM\_100@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 09:49:43

20MHz\_High\_QPSK\_1@99




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 09:53:32

20MHz\_High\_QPSK\_100@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 09:54:26

20MHz\_High\_16QAM\_1@99



ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 09:55:20

20MHz\_High\_16QAM\_100@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 09:56:14

FCC Part 27&IC RSS 199


B7, Normal

5MHz\_Low\_QPSK\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:40:21

5MHz\_Low\_QPSK\_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:40:34

5MHz\_Low\_16QAM\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:40:47

5MHz\_Low\_16QAM\_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:41:00

5MHz\_High\_QPSK\_1@24




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:41:22

5MHz\_High\_QPSK\_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:41:35

5MHz\_High\_16QAM\_1@24




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:41:19

5MHz\_High\_16QAM\_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:42:02

10MHz\_Low\_QPSK\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:42:19

10MHz\_Low\_QPSK\_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:42:42

10MHz\_Low\_16QAM\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:42:56

10MHz\_Low\_16QAM\_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:43:09

10MHz\_High\_QPSK\_1@49




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:43:33

10MHz\_High\_QPSK\_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:43:46

10MHz\_High\_16QAM\_1@49




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:44:00

10MHz\_High\_16QAM\_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:44:14

15MHz\_Low\_QPSK\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:44:40

15MHz\_Low\_QPSK\_75@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:44:53

15MHz\_Low\_16QAM\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:45:07

15MHz\_Low\_16QAM\_75@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:45:21

15MHz\_High\_QPSK\_1@74




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:51:45

15MHz\_High\_QPSK\_75@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:52:29

15MHz\_High\_16QAM\_1@74



ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:53:13


15MHz\_High\_16QAM\_75@0



ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 8.FEB.2025 22:26:50




20MHz\_Low\_QPSK\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 8.FEB.2025 22:27:54

20MHz\_Low\_QPSK\_100@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 8.FEB.2025 22:28:07

20MHz\_Low\_16QAM\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 8.FEB.2025 22:28:20

20MHz\_Low\_16QAM\_100@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 8.FEB.2025 22:28:33

20MHz\_High\_QPSK\_1@99




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 8.FEB.2025 22:31:00

20MHz\_High\_QPSK\_100@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 8.FEB.2025 22:31:53

20MHz\_High\_16QAM\_1@99



ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 8.FEB.2025 22:32:47


20MHz\_High\_16QAM\_100@0



ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 8.FEB.2025 22:33:41


FCC Part 27&IC RSS 130  
B12, Normal

1.4MHz\_Low\_QPSK\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:56:38

1.4MHz\_Low\_QPSK\_6@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:57:15

1.4MHz\_Low\_16QAM\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:57:51

1.4MHz\_Low\_16QAM\_6@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:58:28

1.4MHz\_High\_QPSK\_1@5




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:59:14

1.4MHz\_High\_QPSK\_6@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 10:59:51

1.4MHz\_High\_16QAM\_1@5




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:00:28

1.4MHz\_High\_16QAM\_6@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:01:05

3MHz\_Low\_QPSK\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:01:57

3MHz\_Low\_QPSK\_15@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:02:37

3MHz\_Low\_16QAM\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:03:18

3MHz\_Low\_16QAM\_15@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:03:59

3MHz\_High\_QPSK\_1@14




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:04:47

3MHz\_High\_QPSK\_15@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:05:27

3MHz\_High\_16QAM\_1@14




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:06:07

3MHz\_High\_16QAM\_15@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:06:46

5MHz\_Low\_QPSK\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:15:24

5MHz\_Low\_QPSK\_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:09:40

5MHz\_Low\_16QAM\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:10:25

5MHz\_Low\_16QAM\_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:11:11

5MHz\_High\_QPSK\_1@24




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:39:30

5MHz\_High\_QPSK\_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:40:13

5MHz\_High\_16QAM\_1@24




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:40:57

5MHz\_High\_16QAM\_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:41:40

10MHz\_Low\_QPSK\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:42:13

10MHz\_Low\_QPSK\_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:43:37

10MHz\_Low\_16QAM\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:44:33

10MHz\_Low\_16QAM\_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:45:28

10MHz\_High\_QPSK\_1@49




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:46:29

10MHz\_High\_QPSK\_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:47:24

10MHz\_High\_16QAM\_1@49



ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:48:18


10MHz\_High\_16QAM\_50@0



ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:49:13


FCC Part 27&IC RSS 130  
B17, Normal

5MHz\_Low\_QPSK\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:50:22

5MHz\_Low\_QPSK\_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:51:07

5MHz\_Low\_16QAM\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:51:51

5MHz\_Low\_16QAM\_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:52:35

5MHz\_High\_QPSK\_1@24




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:53:24

5MHz\_High\_QPSK\_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:54:07

5MHz\_High\_16QAM\_1@24



ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:54:50


5MHz\_High\_16QAM\_25@0



ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 11:55:34




10MHz\_Low\_QPSK\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 13:08:00

10MHz\_Low\_QPSK\_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 13:09:08

10MHz\_Low\_16QAM\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 13:10:16

10MHz\_Low\_16QAM\_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 13:11:23

10MHz\_High\_QPSK\_1@49




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 13:12:36

10MHz\_High\_QPSK\_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 13:13:43

10MHz\_High\_16QAM\_1@49



ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 13:14:50


10MHz\_High\_16QAM\_50@0



ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 24.JAN.2025 13:15:56


FCC Part 27&IC RSS 199  
B38, Normal

5MHz\_Low\_QPSK\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 10.FEB.2025 11:39:09

5MHz\_Low\_QPSK\_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 10.FEB.2025 11:40:01

5MHz\_Low\_16QAM\_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 10.FEB.2025 11:40:53

5MHz\_Low\_16QAM\_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 10.FEB.2025 11:41:46

5MHz\_High\_QPSK\_1@24




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 10.FEB.2025 11:42:59

5MHz\_High\_QPSK\_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 10.FEB.2025 11:43:51

5MHz\_High\_16QAM\_1@24




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 10.FEB.2025 11:44:42

5MHz\_High\_16QAM\_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 10.FEB.2025 11:45:33

10MHz\_Low\_QPSK\_1@0



ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 10.FEB.2025 11:46:41

10MHz\_Low\_QPSK\_50@0



ProjectNo.:2402A112525E-RF Tester:Loge Long  
Date: 10.FEB.2025 11:47:29