



10MHz_Low_16QAM_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 11:48:17

10MHz_Low_16QAM_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 11:49:06

10MHz_High_QPSK_1@49




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 11:50:21

10MHz_High_QPSK_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 11:51:15

10MHz_High_16QAM_1@49




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 11:52:11

10MHz_High_16QAM_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 11:53:06

15MHz_Low_QPSK_75@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 13:08:34

15MHz_Low_16QAM_75@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 13:10:12

15MHz_High_QPSK_75@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 13:18:55

15MHz_High_16QAM_1@74




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 13:19:41

15MHz_High_16QAM_75@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 13:20:26

20MHz_Low_QPSK_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 13:21:57

20MHz_Low_QPSK_100@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 13:22:35

20MHz_Low_16QAM_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 13:23:13

20MHz_Low_16QAM_100@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 13:23:51

20MHz_High_QPSK_1@99




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 13:31:28

20MHz_High_QPSK_100@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 13:32:16

20MHz_High_16QAM_1@99



ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 13:33:04


20MHz_High_16QAM_100@0



ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 13:33:52


FCC Part 27&IC RSS 139
B66, Normal

1.4MHz_Low_QPSK_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:06:06

1.4MHz_Low_QPSK_6@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:23:12

1.4MHz_Low_16QAM_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:24:32

1.4MHz_Low_16QAM_6@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:24:54

1.4MHz_High_QPSK_1@5




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:25:14

1.4MHz_High_QPSK_6@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:32:13

1.4MHz_High_16QAM_1@5




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:27:07

1.4MHz_High_16QAM_6@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:27:30

3MHz_Low_QPSK_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:33:30

3MHz_Low_QPSK_15@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:33:57

3MHz_Low_16QAM_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:34:22

3MHz_Low_16QAM_15@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:34:49

3MHz_High_QPSK_1@14




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:35:24

3MHz_High_QPSK_15@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:35:50

3MHz_High_16QAM_1@14




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:36:17

3MHz_High_16QAM_15@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:36:43

5MHz_Low_QPSK_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:37:18

5MHz_Low_QPSK_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:37:43

5MHz_Low_16QAM_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:38:08

5MHz_Low_16QAM_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:38:32

5MHz_High_QPSK_1@24




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:39:05

5MHz_High_QPSK_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:39:30

5MHz_High_16QAM_1@24




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:39:14

5MHz_High_16QAM_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:40:18

10MHz_Low_QPSK_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:41:04

10MHz_Low_QPSK_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:41:40

10MHz_Low_16QAM_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:42:14

10MHz_Low_16QAM_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:42:49

10MHz_High_QPSK_1@49




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:43:30

10MHz_High_QPSK_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:44:04

10MHz_High_16QAM_1@49




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:44:39

10MHz_High_16QAM_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:45:13

15MHz_Low_QPSK_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:46:05

15MHz_Low_QPSK_75@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:46:48

15MHz_Low_16QAM_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:47:12

15MHz_Low_16QAM_75@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:48:15

15MHz_High_QPSK_1@74




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:56:04

15MHz_High_QPSK_75@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:56:47

15MHz_High_16QAM_1@74




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:57:31

15MHz_High_16QAM_75@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 24.JAN.2025 16:58:15

20MHz_Low_QPSK_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 08:37:46

20MHz_Low_QPSK_100@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 08:38:40

20MHz_Low_16QAM_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 08:39:35

20MHz_Low_16QAM_100@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 08:40:29

20MHz_High_QPSK_1@99




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:05:47

20MHz_High_QPSK_100@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:06:41

20MHz_High_16QAM_1@99



ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:07:16


20MHz_High_16QAM_100@0



ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:08:10


FCC Part 27&IC RSS 199
B41, Normal

5MHz_Low_QPSK_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 14:36:22

5MHz_Low_QPSK_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 14:36:59

5MHz_Low_16QAM_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 14:37:36

5MHz_Low_16QAM_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 14:38:13

5MHz_High_QPSK_1@24




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 14:43:27

5MHz_High_QPSK_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 14:45:46

5MHz_High_16QAM_1@24




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 14:48:05

5MHz_High_16QAM_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 14:50:25

10MHz_Low_QPSK_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 14:52:32

10MHz_Low_QPSK_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 14:53:11

10MHz_Low_16QAM_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 14:53:49

10MHz_Low_16QAM_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 14:54:27

10MHz_High_QPSK_1@49




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 15:01:12

10MHz_High_QPSK_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 15:01:52

10MHz_High_16QAM_1@49




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 15:02:32

10MHz_High_16QAM_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 15:03:11

15MHz_Low_QPSK_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 15:15:06

15MHz_Low_QPSK_75@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 15:15:44

15MHz_Low_16QAM_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 15:16:24

15MHz_Low_16QAM_75@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 15:17:02

15MHz_High_QPSK_1@74




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 15:19:46

15MHz_High_QPSK_75@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 15:20:25

15MHz_High_16QAM_1@74




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 15:21:03

15MHz_High_16QAM_75@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 15:21:42

20MHz_Low_QPSK_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 15:25:46

20MHz_Low_QPSK_100@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 15:26:25

20MHz_Low_16QAM_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 15:27:05

20MHz_Low_16QAM_100@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 15:27:46

20MHz_High_QPSK_1@99




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 15:32:22

20MHz_High_QPSK_100@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 15:33:03

20MHz_High_16QAM_1@99



ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 15:33:44

20MHz_High_16QAM_100@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 10.FEB.2025 15:34:25


FCC Part 27N&IC RSS 130

B71, Normal


5MHz_Low_QPSK_1@0




5MHz_Low_QPSK_25@0




5MHz_Low_16QAM_1@0




5MHz_Low_16QAM_25@0




5MHz_High_QPSK_1@24



5MHz_High_QPSK_25@0




5MHz_High_16QAM_1@24




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:14:44

5MHz_High_16QAM_25@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:15:27

10MHz_Low_QPSK_1@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:17:57

10MHz_Low_QPSK_50@0




ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:18:50

10MHz_Low_16QAM_1@0



ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:19:43

10MHz_Low_16QAM_50@0



ProjectNo.:2402A112525E-RF Tester:Loge Long
Date: 25.JAN.2025 09:20:37