

On the module there is a shield soldered to the board. Figure bellow shows the cover mounted and not mounted. This is done during re-flow process at EMS site.



