


EUT INTERNAL PHOTOGRAPHS

EUT Housing and Board View 1



EUT Housing and Board View 2



TRF NO. FCC Page 1 of 12 Report No.: ES190506975W Ver.1.0



EUT Housing and Board View 3




EUT Housing and Board View 4



TRF NO. FCC Page 2 of 12 Report No.: ES190506975W Ver.1.0



EUT Housing and Board View 5




EUT Housing and Board View 9



TRF NO. FCC Page 3 of 12 Report No.: ES190506975W Ver.1.0



EUT Housing and Board View 10




Solder Board-Component View 1



TRF NO. FCC Page 4 of 12 Report No.: ES190506975W Ver.1.0






Solder Board-Component View 3




TRF NO. FCC Page 5 of 12 Report No.: ES190506975W Ver.1.0






Solder Board-Component View 5




TRF NO. FCC Page 6 of 12 Report No.: ES190506975W Ver.1.0




Solder Board-Component View 6






TRF NO. FCC Page 7 of 12 Report No.: ES190506975W Ver.1.0






Solder Board-Component View 9



TRF NO. FCC Page 8 of 12 Report No.: ES190506975W Ver.1.0







TRF NO. FCC Page 9 of 12 Report No.: ES190506975W Ver.1.0



Power source 1









TRF NO. FCC Page 11 of 12 Report No.: ES190506975W Ver.1.0



Antenna





-----The end-----