

Appendix C – SAR Test Setup Photos**Test Position Back 0 mm Gap**

Note: The cable is removed for testing.



Test Position Back (Front View) 0 mm Gap



Test Position Front 0 mm Gap

Note: The cable is removed for testing.




Test Position Left 0 mm Gap

Note: The cable is removed for testing.



Test Position Right 0 mm Gap

Note: The cable is removed for testing.



Test Position Top 47 mm Gap

Note: The cable is removed for testing.



Test Position Bottom 0 mm Gap

**Front of Device**

**Back of Device**