



Band 12_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:01:23

Band 12_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 21.APR.2022 18:01:46

Band 12_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:02:18

Band 12_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 21.APR.2022 18:02:44

Band 12_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:03:15

Band 12_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 21.APR.2022 18:03:44

Band 12_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:04:16

Band 12_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 21.APR.2022 18:04:32

Band 12_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:05:04

Band 12_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 21.APR.2022 18:05:33

Band 12_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:06:07

Band 12_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 21.APR.2022 18:06:39

Band 12_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:07:11

Band 12_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 21.APR.2022 18:07:33

Band 12_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:08:11

Band 12_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 21.APR.2022 18:08:30

Band 12_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:09:01

Band 12_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 21.APR.2022 18:09:23

Band 12_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:10:03

Band 12_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 21.APR.2022 18:10:29

Band 13_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:11:07

Band 13_5 MHz_Low_QPSK_RB25#0_2(763MHz-775MHz)




Date: 22.APR.2022 09:13:58

Band 13_5 MHz_Low_QPSK_RB25#0_3(793MHz-806MHz)




Date: 22.APR.2022 09:20:06

Band 13_5 MHz_Low_QPSK_RB25#0_4(1559MHz-1610MHz)




Date: 22.APR.2022 09:21:27

Band 13_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 21.APR.2022 18:11:30

Band 13_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:12:04

Band 13_5 MHz_Middle_QPSK_RB25#0_2(763MHz-775MHz)




Date: 22.APR.2022 09:14:42

Band 13_5 MHz_Middle_QPSK_RB25#0_3(793MHz-806MHz)




Date: 22.APR.2022 09:19:24

Band 13_5 MHz_Middle_QPSK_RB25#0_4(1559MHz-1610MHz)




Date: 22.APR.2022 09:23:14

Band 13_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 21.APR.2022 18:12:23

Band 13_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:12:52

Band 13_5 MHz_High_QPSK_RB25#0_2(763MHz-775MHz)




Date: 22.APR.2022 09:15:23

Band 13_5 MHz_High_QPSK_RB25#0_3(793MHz-806MHz)




Date: 22.APR.2022 09:18:52

Band 13_5 MHz_High_QPSK_RB25#0_4(1559MHz-1610MHz)




Date: 22.APR.2022 09:24:17

Band 13_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 21.APR.2022 18:13:18

Band 13_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:13:46

Band 13_10 MHz_Middle_QPSK_RB50#0_3(763MHz-775MHz)




Date: 22.APR.2022 09:17:29

Band 13_10 MHz_Middle_QPSK_RB50#0_4(793MHz-806MHz)




Date: 22.APR.2022 09:18:06

Band 13_10 MHz_Middle_QPSK_RB50#0_5(1559MHz-1610MHz)




Date: 22.APR.2022 09:25:11

Band 13_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 21.APR.2022 18:14:12

Band 41_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:49:48

Band 41_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 21.APR.2022 18:50:08

Band 41_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:50:36

Band 41_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 21.APR.2022 18:51:02

Band 41_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:51:27

Band 41_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 21.APR.2022 18:51:46

Band 41_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:52:18

Band 41_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 21.APR.2022 18:52:44

Band 41_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:53:21

Band 41_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 21.APR.2022 18:53:46

Band 41_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:54:23

Band 41_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 21.APR.2022 18:54:45

Band 41_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:55:25

Band 41_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 21.APR.2022 18:55:53

Band 41_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:56:31

Band 41_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 21.APR.2022 18:56:57

Band 41_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:57:38

Band 41_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 21.APR.2022 18:58:13

Band 41_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 21.APR.2022 18:58:52

Band 41_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 21.APR.2022 18:59:24

Band 41_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 21.APR.2022 19:00:02

Band 41_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 21.APR.2022 19:00:27

Band 41_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 21.APR.2022 19:01:08

Band 41_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)



Date: 21.APR.2022 19:01:34