


Appendix A


Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 24.APR.2022 13:11:07

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 24.APR.2022 13:11:24

Band 2_1.4 MHz_Middle_QPSK_RB6#0




Date: 24.APR.2022 13:11:41

Band 2_1.4 MHz_Middle_16QAM_RB6#0




Date: 24.APR.2022 13:12:04

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 24.APR.2022 13:12:27

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 24.APR.2022 13:12:47

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 24.APR.2022 13:13:12

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 24.APR.2022 13:13:32

Band 2_3 MHz_Middle_QPSK_RB15#0




Date: 24.APR.2022 13:13:59

Band 2_3 MHz_Middle_16QAM_RB15#0




Date: 24.APR.2022 13:14:16

Band 2_3 MHz_High_QPSK_RB15#0




Date: 24.APR.2022 13:14:36

Band 2_3 MHz_High_16QAM_RB15#0




Date: 24.APR.2022 13:14:56

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 24.APR.2022 13:15:27

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 24.APR.2022 13:15:56

Band 2_5 MHz_Middle_QPSK_RB25#0




Date: 24.APR.2022 13:16:17

Band 2_5 MHz_Middle_16QAM_RB25#0




Date: 24.APR.2022 13:16:40

Band 2_5 MHz_High_QPSK_RB25#0




Date: 24.APR.2022 13:17:06

Band 2_5 MHz_High_16QAM_RB25#0




Date: 24.APR.2022 13:17:33

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 24.APR.2022 13:18:02

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 24.APR.2022 13:18:28

Band 2_10 MHz_Middle_QPSK_RB50#0




Date: 24.APR.2022 13:18:57

Band 2_10 MHz_Middle_16QAM_RB50#0




Date: 24.APR.2022 13:19:25

Band 2_10 MHz_High_QPSK_RB50#0




Date: 24.APR.2022 13:19:51

Band 2_10 MHz_High_16QAM_RB50#0




Date: 24.APR.2022 13:20:22

Band 2 15 MHz Low QPSK RB75#0




Date: 24.APR.2022 13:20:56

Band 2 15 MHz Low 16QAM RB75#0




Date: 24.APR.2022 13:21:32

Band 2_15 MHz_Middle_QPSK_RB75#0




Date: 24.APR.2022 13:22:09

Band 2_15 MHz_Middle_16QAM_RB75#0




Date: 24.APR.2022 13:22:45

Band 2_15 MHz_High_QPSK_RB75#0




Date: 24.APR.2022 13:23:12

Band 2_15 MHz_High_16QAM_RB75#0




Date: 24.APR.2022 13:23:38

Band 2_20 MHz_Middle_QPSK_RB100#0




Date: 24.APR.2022 13:25:11

Band 2_20 MHz_Middle_16QAM_RB100#0




Date: 24.APR.2022 13:25:47

Band 2_20 MHz_High_QPSK_RB100#0




Date: 24.APR.2022 13:26:17

Band 2_20 MHz_High_16QAM_RB100#0




Date: 24.APR.2022 13:26:56

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 24.APR.2022 13:27:15

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 24.APR.2022 13:27:32

Band 5_1.4 MHz_Middle_QPSK_RB6#0



Date: 24.APR.2022 13:27:50

Band 5_1.4 MHz_Middle_16QAM_RB6#0



Date: 24.APR.2022 13:28:10