



Band 12_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:22:48

Band 12_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:23:10

Band 12_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:23:43

Band 12_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:24:02

Band 12_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:24:34

Band 12_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:25:02

Band 12_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:25:37

Band 12_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:26:02

Band 12_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:26:35

Band 12_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:27:00

Band 12_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:27:29

Band 12_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:27:51

Band 12_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:28:23

Band 12_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:28:39

Band 12_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:29:13

Band 12_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:29:36

Band 12_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:30:10

Band 12_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:30:35

Band 12_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:31:09

Band 12_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:31:31

Band 13_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:32:04

Band 13_5 MHz_Low_QPSK_RB25#0_2(763MHz-775MHz)




Date: 25.APR.2022 16:29:51

Band 13_5 MHz_Low_QPSK_RB25#0_3(793MHz-806MHz)




Date: 25.APR.2022 16:33:44

Band 13_5 MHz_Low_QPSK_RB25#0_4(1559MHz-1610MHz)




Date: 25.APR.2022 16:36:30

Band 13_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:32:26

Band 13_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:33:01

Band 13_5 MHz_Middle_QPSK_RB25#0_2(763MHz-775MHz)




Date: 25.APR.2022 16:30:48

Band 13_5 MHz_Middle_QPSK_RB25#0_3(793MHz-806MHz)




Date: 25.APR.2022 16:32:42

Band 13_5 MHz_Middle_QPSK_RB25#0_4(1559MHz-1610MHz)




Date: 25.APR.2022 16:37:06

Band 13_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:33:23

Band 13_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:33:55

Band 13_5 MHz_High_QPSK_RB25#0_2(763MHz-775MHz)




Date: 25.APR.2022 16:31:48

Band 13_5 MHz_High_QPSK_RB25#0_3(793MHz-806MHz)




Date: 25.APR.2022 16:32:22

Band 13_5 MHz_High_QPSK_RB25#0_4(1559MHz-1610MHz)




Date: 25.APR.2022 16:37:43

Band 13_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:34:11

Band 13_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 25.APR.2022 16:40:07

Band 13_10 MHz_Middle_QPSK_RB50#0_3(763MHz-775MHz)




Date: 25.APR.2022 16:44:00

Band 13_10 MHz_Middle_QPSK_RB50#0_4(793MHz-806MHz)




Date: 25.APR.2022 16:41:23

Band 13_10 MHz_Middle_QPSK_RB50#0_5(1559MHz-1610MHz)




Date: 25.APR.2022 17:08:05

Band 13_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:35:02

Band 41_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.APR.2022 16:20:31

Band 41_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 24.APR.2022 16:20:59

Band 41_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.APR.2022 16:21:37

Band 41_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 24.APR.2022 16:22:03

Band 41_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.APR.2022 16:22:40

Band 41_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 24.APR.2022 16:23:09

Band 41_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 24.APR.2022 16:23:47

Band 41_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 24.APR.2022 16:24:09

Band 41_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 24.APR.2022 16:24:40

Band 41_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 24.APR.2022 16:25:02

Band 41_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 24.APR.2022 16:25:50

Band 41_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 24.APR.2022 16:26:19

Band 41_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 24.APR.2022 16:27:01

Band 41_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 24.APR.2022 16:27:26

Band 41_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 24.APR.2022 16:28:05

Band 41_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 24.APR.2022 16:28:33

Band 41_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 24.APR.2022 16:29:11

Band 41_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 24.APR.2022 16:29:34

Band 41_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 24.APR.2022 16:30:13

Band 41_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 24.APR.2022 16:30:35

Band 41_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 24.APR.2022 16:31:20

Band 41_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 24.APR.2022 16:31:42

Band 41_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 24.APR.2022 16:32:23

Band 41_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)



Date: 24.APR.2022 16:32:49