


Appendix B


Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 14.APR.2022 11:59:58

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 14.APR.2022 12:00:27

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 14.APR.2022 12:00:59

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 14.APR.2022 12:01:15

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 14.APR.2022 12:01:46

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 14.APR.2022 12:02:15

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 14.APR.2022 12:02:50

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 14.APR.2022 12:03:12

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 14.APR.2022 12:03:53

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 14.APR.2022 12:04:15

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 14.APR.2022 12:04:44

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 14.APR.2022 12:05:12

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.APR.2022 12:05:43

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 14.APR.2022 12:06:08

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.APR.2022 12:06:40

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 14.APR.2022 12:07:02

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 14.APR.2022 12:07:37

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 14.APR.2022 12:07:59

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 14.APR.2022 12:08:33

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 14.APR.2022 12:08:53

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 14.APR.2022 12:09:27

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 14.APR.2022 12:09:52

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 14.APR.2022 12:10:26

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 14.APR.2022 12:10:48

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 14.APR.2022 12:11:24

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 14.APR.2022 12:11:53

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 14.APR.2022 12:12:25

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 14.APR.2022 12:12:56

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 14.APR.2022 12:13:32

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 14.APR.2022 12:14:00

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 14.APR.2022 12:14:39

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 14.APR.2022 12:15:04

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 14.APR.2022 12:15:46

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 14.APR.2022 12:16:08

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 14.APR.2022 12:16:44

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 14.APR.2022 12:17:03

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 14.APR.2022 12:17:41

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 14.APR.2022 12:18:07

Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 14.APR.2022 12:18:39

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 14.APR.2022 12:18:58

Band 5 1.4 MHz High QPSK RB6#0 1(30MHz-1GHz)



Date: 14.APR.2022 12:19:33

Band 5 1.4 MHz High QPSK RB6#0 2(1GHz-10GHz)



Date: 14.APR.2022 12:20:01

