

FCC Label:

Midea MICROWAVE OVEN MODEL:EM234GTQ-S POWER SUPPLY:120V~ 60Hz RATED INPUT(MICROWAVE):2050W RATED OUTPUT(MICROWAVE):1200W MICROWAVE OUTPUT FREQUENCY:2450MHz MANUFACTURE DATE:MM.YYYY FCC ID:2AULTEM234GY COMMERCIAL USE THIS DEVICE COMPLIES WITH DHHS RADIATION PERFORMANCE STANDARDS 21 CFR SUBCHAPTER J. MADE IN THAILAND THAI TOSHIBA ELECTRIC INDUSTRIES CO.,LTD. 129/1-5, Triwanon Road, Ta Sai Sub-District, Mueang Nonthaburi District, Nonthaburi Province, 11000 Thailand WARNING:Cancer and Reproductive Harm-www.p65warnings.ca.gov	CAUTION - THIS DEVICE IS TO BE SERVICED ONLY BY PROPERLY QUALIFIED SERVICE PERSONNEL. CONSULT THE SERVICE MANUAL FOR PROPER SERVICE PROCEDURES TO ASSURE CONTINUED COMPLIANCE WITH THE FEDERAL PERFORMANCE STANDARD FOR MICROWAVE OVENS AND FOR PRECAUTIONS TO BE TAKEN TO AVOID POSSIBLE EXPOSURE TO EXCESSIVE MICROWAVE ENERGY. WARNING - TO ENSURE CONTINUED PROTECTION AGAINST ELECTRICAL SHOCK HAZARD, CONNECT TO PROPERLY GROUNDED OUTLETS ONLY. DISCONNECT APPLIANCE BEFORE SERVICING. REMOVAL OF OUTER CASE WITH PRODUCT ENERGIZED MAY EXPOSE SERVICEMAN TO HAZARDOUS HIGH VOLTAGE POTENTIALS. • CERTAIN INTERNAL PARTS ARE INTENTIONALLY NOT GROUNDED AND MAY PRESENT A RISK OF ELECTRIC SHOCK ONLY DURING SERVICING. SERVICE PERSONNEL - DO NOT CONTACT THE FOLLOWING PARTS WHILE THE APPLIANCE IS ENERGIZED: IF PROVIDED FAN MOTOR, TURNABLE MOTOR, DAMPER MOTOR, L.V. TRANSFORMER (TOUCH CONTROL TYPE) OR TIMER MOTOR ASSEMBLY (MECHANICAL TYPE). • RISK OF ELECTRIC SHOCK. NON-REMOVABLE FASTENERS ARE PROVIDED BECAUSE OF INTERNAL HIGH VOLTAGES. DO NOT REMOVE FASTENERS. • NOT FOR BUILT-IN INSTALLATION. CAUTION - Hot
---	---

FCC Label Location:

