

INTERTEK TESTING SERVICE

Report No.: HK19100315

Equipment Photographs

(External)



INTERTEK TESTING SERVICE

Report No.: HK19100315

Equipment Photographs

(External)



INTERTEK TESTING SERVICE

Report No.: HK19100315

Equipment Photographs

(External)




INTERTEK TESTING SERVICE

Report No.: HK19100315

Equipment Photographs

(External)



Roto Base - bottom sticker

W 62 x H 57 (mm)

roto

www.rotovr.com

Model: RotoA001


FCC ID: 2AUNZROTOA001

MADE IN CHINA / FABRIQUE EN CHINE

FCC AND IC STATEMENT:

- i. This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.
- ii. CAN ICES-3(B)/NMB-3(B)





Label location