



22215 26TH AVE SE | SUITE 100 & 200
BOTHELL, WA 98021 | USA
www.pivotalthcommware.com

September 18th, 2023

To:

Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046

Subject: **Attestation Letter for Signal Booster Warning Label**

Product: **Pivot 5G – Service Unit (Model Number: 5620-23-39)**

FCC ID: **2AUVU-5620-23-39**

To Whom It May Concern,

Pursuant to **47 CFR §20.21(f)(1)(i-iv)**, this letter is to confirm that **Pivotal Commware** hereby attests that the warning label message will be shown in the following locations:

- In online, point-of-sale marketing materials
- In the Quick Start Guide (printed) and User's Manual (online)
- On the outside packaging of the device
- On a label affixed to the device

Pursuant to **47 CFR §20.21(f)(1)(iv)(B)**, the Industrial Signal Booster (ISB) warning label message shall read:

WARNING. This is NOT a CONSUMER device. It is designed for installation by FCC LICENSEES and QUALIFIED INSTALLERS. You MUST have an FCC LICENSE or express consent of an FCC Licensee to operate this device. Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation.

Sincerely,
DocuSigned by:

Sean Ford

429B504B2C31408...
Sean Ford

VP of Finance
Pivotal Commware, Inc.