




n41\_30kHz\_SISO\_NTNV\_60MHz\_DFT-s-OFDM\_64\_QAM\_2526MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_60MHz\_DFT-s-OFDM\_64\_QAM\_2592.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_60MHz\_DFT-s-OFDM\_64\_QAM\_2659.98MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_60MHz\_DFT-s-OFDM\_256\_QAM\_2526MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_60MHz\_DFT-s-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_60MHz\_DFT-s-OFDM\_256\_QAM\_2659.98MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_QPSK\_2526MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_QPSK\_2592.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_QPSK\_2659.98MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_16\_QAM\_2526MHz\_Outer\_Full\_Ant3




# n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant3




# n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_16\_QAM\_2659.98MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_64\_QAM\_2526MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_64\_QAM\_2592.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_64\_QAM\_2659.98MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_256\_QAM\_2526MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_256\_QAM\_2659.98MHz\_Outer\_Full\_Ant3




3.2.6 30k\_SISO\_70MHz\_NTNV




n41\_30kHz\_SISO\_NTNV\_70MHz\_DFT-s-OFDM\_QPSK\_2655MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_70MHz\_DFT-s-OFDM\_16\_QAM\_2531.01MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_70MHz\_DFT-s-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_70MHz\_DFT-s-OFDM\_16\_QAM\_2655MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_70MHz\_DFT-s-OFDM\_64\_QAM\_2531.01MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_70MHz\_DFT-s-OFDM\_64\_QAM\_2592.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_70MHz\_DFT-s-OFDM\_64\_QAM\_2655MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_70MHz\_DFT-s-OFDM\_256\_QAM\_2531.01MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_70MHz\_DFT-s-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_70MHz\_DFT-s-OFDM\_256\_QAM\_2655MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM\_QPSK\_2531.01MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM\_QPSK\_2592.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM\_QPSK\_2655MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM\_16\_QAM\_2531.01MHz\_Outer\_Full\_Ant3




# n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant3




# n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM\_16\_QAM\_2655MHz\_Outer\_Full\_Ant3




# n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM\_64\_QAM\_2531.01MHz\_Outer\_Full\_Ant3




# n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM\_64\_QAM\_2592.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM 64 QAM 2655MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM 256 QAM 2531.01MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM\_256\_QAM\_2655MHz\_Outer\_Full\_Ant3




3.2.7 30k\_SISO\_80MHz\_NTNV




n41\_30kHz\_SISO\_NTNV\_80MHz\_DFT-s-OFDM\_QPSK\_2649.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_80MHz\_DFT-s-OFDM\_16\_QAM\_2536.02MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_80MHz\_DFT-s-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_80MHz\_DFT-s-OFDM\_16\_QAM\_2649.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_80MHz\_DFT-s-OFDM\_64\_QAM\_2536.02MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_80MHz\_DFT-s-OFDM\_64\_QAM\_2592.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_80MHz\_DFT-s-OFDM\_64\_QAM\_2649.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_80MHz\_DFT-s-OFDM\_256\_QAM\_2536.02MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_80MHz\_DFT-s-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_80MHz\_DFT-s-OFDM\_256\_QAM\_2649.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_80MHz\_CP-OFDM\_QPSK\_2536.02MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_80MHz\_CP-OFDM\_QPSK\_2592.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_80MHz\_CP-OFDM\_QPSK\_2649.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_80MHz\_CP-OFDM\_16\_QAM\_2536.02MHz\_Outer\_Full\_Ant3




# n41\_30kHz\_SISO\_NTNV\_80MHz\_CP-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant3




# n41\_30kHz\_SISO\_NTNV\_80MHz\_CP-OFDM\_16\_QAM\_2649.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_80MHz\_CP-OFDM\_64\_QAM\_2536.02MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_80MHz\_CP-OFDM\_64\_QAM\_2592.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_80MHz\_CP-OFDM\_64\_QAM\_2649.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_80MHz\_CP-OFDM\_256\_QAM\_2536.02MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_80MHz\_CP-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_80MHz\_CP-OFDM\_256\_QAM\_2649.99MHz\_Outer\_Full\_Ant3




3.2.8 30k\_SISO\_90MHz\_NTNV




n41\_30kHz\_SISO\_NTNV\_90MHz\_DFT-s-OFDM\_QPSK\_2644.98MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_90MHz\_DFT-s-OFDM\_16\_QAM\_2541MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_90MHz\_DFT-s-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_90MHz\_DFT-s-OFDM\_16\_QAM\_2644.98MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_90MHz\_DFT-s-OFDM\_64\_QAM\_2541MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_90MHz\_DFT-s-OFDM\_64\_QAM\_2592.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_90MHz\_DFT-s-OFDM\_64\_QAM\_2644.98MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_90MHz\_DFT-s-OFDM\_256\_QAM\_2541MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_90MHz\_DFT-s-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_90MHz\_DFT-s-OFDM\_256\_QAM\_2644.98MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_90MHz\_CP-OFDM\_QPSK\_2541MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_90MHz\_CP-OFDM\_QPSK\_2592.99MHz\_Outer\_Full\_Ant3




n41\_30kHz\_SISO\_NTNV\_90MHz\_CP-OFDM\_QPSK\_2644.98MHz\_Outer\_Full\_Ant3



n41\_30kHz\_SISO\_NTNV\_90MHz\_CP-OFDM\_16\_QAM\_2541MHz\_Outer\_Full\_Ant3



# n41\_30kHz\_SISO\_NTNV\_90MHz\_CP-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant3



# n41\_30kHz\_SISO\_NTNV\_90MHz\_CP-OFDM\_16\_QAM\_2644.98MHz\_Outer\_Full\_Ant3

