



1. Appendix: WPT SETUP PHOTOS

1) RADIATED RF MEASUREMENT SETUP

FACE ON TEST PHOTO



FACE OFF TEST PHOTO



2) RADIATED RF MEASUREMENT SET-UP (Axis)

X AXIS PHOTO



Y AXIS PHOTO




Z AXIS PHOTO




3) AC LINE CONDUCTED MEASUREMENT SETUP

AC LINE CONDUCTED FRONT TEST PHOTO



AC LINE CONDUCTED REAR TEST PHOTO



END OF TEST PHOTO