




Appendix I Radiated Band Edge and OOB Measurement

Dipole Antenna

802.11a

Peak




Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000


Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0





Test report No. : 4789507582-US-R1-V0
Page : 141 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000


Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0




Test report No. : 4789507582-US-R1-V0
Page : 142 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324


Ch149



Ch157



Ch165



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Average



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789507582-US-R1-V0
Page : 144 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000


Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



802.11n (HT20)


Peak






Test report No. : 4789507582-US-R1-V0
Page : 146 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324


Ch52



Ch60



Ch64



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000


Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0




Test report No. : 4789507582-US-R1-V0
Page : 147 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324


Ch100



Ch116



Ch140



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000


Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0




Test report No. : 4789507582-US-R1-V0
Page : 148 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324


Ch149



Ch157



Ch165



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0




Average





Test report No. : 4789507582-US-R1-V0
Page : 150 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000


Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



802.11n (HT40)


Peak






Test report No. : 4789507582-US-R1-V0
Page : 152 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324


Ch62



Ch102



Ch110



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000


Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0




Test report No. : 4789507582-US-R1-V0
Page : 153 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324


Ch134



Ch151



Ch159



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Average



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789507582-US-R1-V0
Page : 155 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000


Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0




802.11ac (VHT80)

Peak





Test report No. : 4789507582-US-R1-V0
Page : 157 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Average



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948


Doc No: 17-EM-F0878 / 5.0



PIFA Antenna

802.11a

Peak



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789507582-US-R1-V0
Page : 160 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789507582-US-R1-V0
Page : 161 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000


Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0




Test report No. : 4789507582-US-R1-V0
Page : 162 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324


Ch149



Ch157



Ch165



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0




Average





Test report No. : 4789507582-US-R1-V0
Page : 164 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000


Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



802.11n (HT20)


Peak






Test report No. : 4789507582-US-R1-V0
Page : 166 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324


Ch52



Ch60



Ch64



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789507582-US-R1-V0
Page : 167 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000


Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0




Test report No. : 4789507582-US-R1-V0
Page : 168 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324


Ch149



Ch157



Ch165



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0




Average





Test report No. : 4789507582-US-R1-V0
Page : 170 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



802.11n (HT40)

Peak

