





Test report No. : 4789507582-US-R1-V0
Page : 172 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324


Ch62



Ch102



Ch110



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948


Doc No: 17-EM-F0878 / 5.0




Ch134



Ch151




Ch159





Test report No. : 4789507582-US-R1-V0
Page : 174 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324

Average




Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948


Doc No: 17-EM-F0878 / 5.0






802.11ac (VHT80)

Peak





Test report No. : 4789507582-US-R1-V0
Page : 177 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Average



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948


Doc No: 17-EM-F0878 / 5.0



Appendix II Radiated Spurious Emission Measurement


Dipole Antenna

802.11a





Test report No. : 4789507582-US-R1-V0
Page : 180 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789507582-US-R1-V0
Page : 181 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948


Doc No: 17-EM-F0878 / 5.0




Ch149



Ch157




Ch165






802.11n (HT20)





Test report No. : 4789507582-US-R1-V0
Page : 184 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789507582-US-R1-V0
Page : 185 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789507582-US-R1-V0
Page : 186 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0




802.11n (HT40)





Test report No. : 4789507582-US-R1-V0
Page : 188 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789507582-US-R1-V0
Page : 189 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



802.11ac (VHT80)



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789507582-US-R1-V0
Page : 191 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000


Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



PIFA Antenna

802.11a




Underwriters Laboratories Taiwan Co., Ltd.


Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0










Test report No. : 4789507582-US-R1-V0
Page : 196 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324

802.11n (HT20)



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789507582-US-R1-V0
Page : 197 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789507582-US-R1-V0
Page : 198 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324




Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000


Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0






802.11n (HT40)





Test report No. : 4789507582-US-R1-V0
Page : 201 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948


Doc No: 17-EM-F0878 / 5.0




Ch134



Ch151




Ch159





802.11ac (VHT80)



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0



Test report No. : 4789507582-US-R1-V0
Page : 204 of 204
Issued date : Dec. 15, 2020
FCC ID : 2AWKZ-QCNFA324



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone : +886-2-7737-3000

Facsimile (FAX) : +886-3-583-7948

Doc No: 17-EM-F0878 / 5.0