

Company Name: Shenzhen Awell Technology Limited
Add: B316, Jinbolong Industrial Area, No. 1, Huayun Road, Yucui Community, Longhua, Shenzhen
Tel:15920020520
Eail: 625340878@qq.com

Date: 2020-11-05

FEDERAL COMMUNICATIONS COMMISSIONS
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046

To whom it may concern:

The RF chip, model RTL8762, which installed in our product SMART WATCH, Model: B53, B1, B2, B5, B6, B9, B10, B11, B12, B15, B16, B19, B20, B21, B22, B26, B29, B30, B31, B32, B35, B36, B39, B40, B51, B52, B55, B56, B59, B61, B63, B65, B66, B69, B70, B71, B72, B75, B76, B79, B80, B81, B82, B85, B86, B89, B90, B91, B92, B95, B96, B99, B100, B101, B102, B105, B106, B109, B111, B112, B115, B116, B120, B121, B122, B125, B126, B129, B130, B131, B132, B135, B136, B139, B140, B141, B142, B145, B146, B149, B150, B151, B152, B155, B156, B159, B160, B161, B162, B165, B166, B169, B170, B171, B172, B175, B176, B179, B180, B181, B182, B185, B186, B189, B190, B191, B192, B195, B196, B199, FCC ID: 2AX3N-B53, supports BDR (GFSK), EDR ($\pi/4$ -DQPSK, 8DPSK), and BLE functions. For use in America, this chip will not support BDR (GFSK), EDR ($\pi/4$ -DQPSK, 8DPSK). The BDR (GFSK), EDR ($\pi/4$ -DQPSK, 8DPSK) function was disabled to use by manufacture.

Sincerely,

Signature: 

Contact person: qipeng hu

Title: PM