

INTERNAL PHOTOS BLASTER RF915

Rev.: 0 (16/04/2020) EN

Rev.:	Date	Control of changes and modifications.
0	16/04/2020	Creation and revision of the document.

Prepared	Reviewed	Approved
Jon Eritz Fernández Linares Electronic Professional 16/04/2020		


© MAXAM Corp Holding, S.L. This document is owned by MAXAM, and is for the exclusive use of its staff. The information contained herein may not be reproduced or transmitted by any means outside of MAXAM without express permission. The controlled copy of this document is officially published in MAXAM Place in its electronic format.




INDEX

1. General view.....	3
2. Mainboard module.....	5
2.1. Top view.....	5
2.2. Bottom view.....	6
3. Keyboard module.....	7
3.1. Top view.....	7
3.2. Bottom view.....	8
4. NFC module.....	9
4.1. Top view.....	9
4.2. Bottom view.....	9
4.3. Component identification.....	10
5. RF915 module.....	11
5.1. Top view.....	11
5.2. Bottom view.....	12
5.3. Component identification.....	13


1. General view.






2. Mainboard module.

2.1. Top view.




2.2. Bottom view.



3. Keyboard module.

3.1. Top view.




3.2. Bottom view.



4. NFC module.


4.1. Top view.



4.2. Bottom view.




4.3. Component identification.



5. RF915 module.

5.1. Top view.



5.2. Bottom view.



5.3. Component identification.

