

## TP-Link Corporation Limited

Federal Communications Commission  
7435 Oakland Mills Road  
Columbia MD 21046

American Certification Body, Inc.  
6731 Whittier Avenue  
Suite C110  
McLean, VA 22101

Subject: Requesting Class II permissive change for FCC ID: 2AXJ4C80V2

To Whom It May Concern:

The purpose of this letter is to request a Class II Permissive change for FCC ID: 2AXJ4C80V2, original granted on 05/05/2022.

There is no other hardware or electrical modification made to the applying transmitter itself except below:

1. Changed the transformer: The LAN port plug-in transformer is changed to a surface mount capacitor separated transformer, and the WAN port 18-pin transformer is changed to a small 20-pin transformer.

Please contact me if you have any questions or need further information regarding this application.

Best Regards,

Name: Sarah Wang

Function: Regulatory Compliance Manager

Date: 2025-06-16

Signed: 