

Nemko Canada 303 River Road Ottawa, Ontario, Canada K1V 1H2

Request for Change in identification of equipment

Pursuant to FCC 47 CFR 2.933(b) Gimasi SA having a business address at Piazzale Roncaa 4 – 6850, Mendrisio – Switzerland, hereby requests a change in identification.

The new FCC identifier is FCC ID: 2AXU7-THENODE

- (1) The original identification used on the equipment prior to the change in identification is: FCC ID: XMR201910BG95M3, Grant issued on 2019-10-17
- (2) The equipment bearing the modified identification is identical to the original equipment.
- (3) The original test results continue to be representative of and applicable to the equipment bearing the changed identification.
- (4) Photographs showing the exterior appearance of the equipment and the identification label are included in this application.

Dated this	29	Day of July	20	21	
Ву: _	Mounter		Massimo Santoli Printed	ssimo Santoli Printed	
Title:	CEO				
On bel	half of :	GIMASI SA			
Teleph	one: _+417	66757832			