






































Band 13_5 MHz_Low_QPSK_RB1#0_3(763MHz-775MHz)




ProjectNo.:2401S24086-RF Tester:Allen Bai
Date: 6.AUG.2024 23:13:23

Band 13_5 MHz_Low_QPSK_RB1#0_4(793MHz-806MHz)




ProjectNo.:2401S24086-RF Tester:Allen Bai
Date: 6.AUG.2024 23:13:42

Band 13_5 MHz_Low_QPSK_RB1#0_5(1.559GHz-1.61GHz)




ProjectNo.:2401S24086-RF Tester:Allen Bai
Date: 7.AUG.2024 03:16:36

Band 13_5 MHz_Middle_QPSK_RB1#0_3(763MHz-775MHz)




ProjectNo.:2401S24086-RF Tester:Allen Bai
Date: 6.AUG.2024 23:15:10

Band 13_5 MHz_Middle_QPSK_RB1#0_4(793MHz-806MHz)




ProjectNo.:2401S24086-RF Tester:Allen Bai
Date: 6.AUG.2024 23:15:32

Band 13_5 MHz_Middle_QPSK_RB1#0_5(1.559GHz-1.61GHz)




ProjectNo.:2401S24086-RF Tester:Allen Bai
Date: 7.AUG.2024 03:16:00

Band 13_5 MHz_High_QPSK_RB1#0_3(763MHz-775MHz)




ProjectNo.:2401S24086-RF Tester:Allen Bai
Date: 6.AUG.2024 23:17:13

Band 13_5 MHz_High_QPSK_RB1#0_4(793MHz-806MHz)




ProjectNo.:2401S24086-RF Tester:Allen Bai
Date: 6.AUG.2024 23:17:38

Band 13_5 MHz_High_QPSK_RB1#0_5(1.559GHz-1.61GHz)




ProjectNo.:2401S24086-RF Tester:Allen Bai
Date: 7.AUG.2024 03:17:18

Band 13_10 MHz_Middle_QPSK_RB1#0_3(763MHz-775MHz)




ProjectNo.:2401S24086-RF Tester:Allen Bai
Date: 6.AUG.2024 23:19:48

Band 13_10 MHz_Middle_QPSK_RB1#0_4(793MHz-806MHz)



ProjectNo.:2401S24086-RF Tester:Allen Bai
Date: 6.AUG.2024 23:20:14

Band 13_10 MHz_Middle_QPSK_RB1#0_5(1.559GHz-1.61GHz)



ProjectNo.:2401S24086-RF Tester:Allen Bai
Date: 7.AUG.2024 03:17:41