



Report No.: AAEMT/EMC/221003-01-08

6dB BW 802.11ac80
Channel: 155




Report No.: AAEMT/EMC/221003-01-08

6dB BW 802.11ax20
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/221003-01-08


Channel: 165




Report No.: AAEMT/EMC/221003-01-08

6dB BW 802.11ax40

Channel: 151




Channel: 159




Report No.: AAEMT/EMC/221003-01-08

6dB BW 802.11ax80
Channel: 155




6dB BW 802.11ax160
Channel: 163




Test plots as followed: CHAIN 1

6dB BW 802.11a

Channel: 149




Channel: 157




Report No.: AAEMT/EMC/221003-01-08

Channel: 165




Report No.: AAEMT/EMC/221003-01-08

6dB BW 802.11n20
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/221003-01-08


Channel: 165




Report No.: AAEMT/EMC/221003-01-08

6dB BW 802.11n40

Channel: 151




Channel: 159




Report No.: AAEMT/EMC/221003-01-08

6dB BW 802.11ac20
Channel: 149




Channel: 157




Report No.: AAEMT/EMC/221003-01-08

Channel: 165




Report No.: AAEMT/EMC/221003-01-08

6dB BW 802.11ac40
Channel: 151




Channel: 159




Report No.: AAEMT/EMC/221003-01-08

6dB BW 802.11ac80
Channel: 155




Report No.: AAEMT/EMC/221003-01-08

6dB BW 802.11ax20
Channel: 149




Channel: 157




Report No.: AAEMT/EMC/221003-01-08

Channel: 165




Report No.: AAEMT/EMC/221003-01-08

6dB BW 802.11ax40
Channel: 151




Channel: 159



Report No.: AAEMT/EMC/221003-01-08


6dB BW 802.11ax80

Channel: 155



6dB BW 802.11ax160

Channel: 163




Report No.: AAEMT/EMC/221003-01-08


Test plots as followed: CHAIN 0

99% OBW 802.11a

Channel: 36




Channel: 44



Report No.: AAEMT/EMC/221003-01-08


Channel: 48




Report No.: AAEMT/EMC/221003-01-08

99% OBW 802.11n20

Channel: 36




Channel: 44



Report No.: AAEMT/EMC/221003-01-08


Channel: 48




Report No.: AAEMT/EMC/221003-01-08

99% OBW 802.11n40

Channel: 38




Channel: 46




Report No.: AAEMT/EMC/221003-01-08

99% OBW 802.11ac20

Channel: 36




Channel: 44




Report No.: AAEMT/EMC/221003-01-08

Channel: 48




Report No.: AAEMT/EMC/221003-01-08

99% OBW 802.11ac40
Channel: 38




Channel: 46




Report No.: AAEMT/EMC/221003-01-08

99% OBW 802.11ac80
Channel: 42




Report No.: AAEMT/EMC/221003-01-08

99% OBW 802.11ax20
Channel: 36




Channel: 44



Report No.: AAEMT/EMC/221003-01-08


Channel: 48




Report No.: AAEMT/EMC/221003-01-08

99% OBW 802.11ax40

Channel: 38




Channel: 46




Report No.: AAEMT/EMC/221003-01-08

99% OBW 802.11ax80
Channel: 42




99% OBW 802.11ax160
Channel: 50




Test plots as followed: CHAIN 0

99% OBW 802.11a

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/221003-01-08


Channel: 165




Report No.: AAEMT/EMC/221003-01-08

99% OBW 802.11n20

Channel: 149




Channel: 157



Report No.: AAEMT/EMC/221003-01-08


Channel: 165




Report No.: AAEMT/EMC/221003-01-08

99% OBW 802.11n40

Channel: 151




Channel: 159




Report No.: AAEMT/EMC/221003-01-08

99% OBW 802.11ac20
Channel: 149




Channel: 157



Report No.: AAEMT/EMC/221003-01-08


Channel:165




Report No.: AAEMT/EMC/221003-01-08

99% OBW 802.11ac40

Channel:151




Channel:159



Report No.: AAEMT/EMC/221003-01-08


99% OBW 802.11ac80
Channel:155




Report No.: AAEMT/EMC/221003-01-08

99% OBW 802.11ax20

Channel:149




Channel: 157



Report No.: AAEMT/EMC/221003-01-08


Channel: 165




Report No.: AAEMT/EMC/221003-01-08

99% OBW 802.11ax40

Channel: 151




Channel: 159



Report No.: AAEMT/EMC/221003-01-08


99% OBW 802.11ax80

Channel: 155




99% OBW 802.11ax160

Channel: 163




Test plots as followed: CHAIN 1

99% OBW 802.11a Channel: 36




Channel: 44




Report No.: AAEMT/EMC/221003-01-08

Channel: 48




99% OBW 802.11n20

Channel: 36




Report No.: AAEMT/EMC/221003-01-08

Channel: 44




Channel: 48




Report No.: AAEMT/EMC/221003-01-08

99% OBW 802.11n40

Channel: 38




Channel: 46




Report No.: AAEMT/EMC/221003-01-08

99% OBW 802.11ac20

Channel: 36




Channel: 44



Report No.: AAEMT/EMC/221003-01-08

Channel: 48



99% OBW 802.11ac40

Channel: 38

