


# 06.11.01.1479 料号 K932T 孟加拉 说明书尺寸78x120mm 展开468x120mm 材质128克双铜纸单黑印刷








MODE SWITCHING METHOD OF THE KEYBOARD

IOS/MAC/WIN LAYOUT SWITCH

 $iOS: \binom{r_0}{r_0} + \binom{0}{0}$  Mac:  $\binom{r_0}{r_0} + \binom{1}{n}$  Win:  $\binom{r_0}{r_0} + \binom{p}{n}$ 



1. The factory default setting of F1-F12/ multimedia function keys is multimedia function.



## PACKAGING CONTENTS

- . Wireless keyboard
- USB-A 2.0 receiver
  2×AAA batteries
  Instruction manual

- USB port
  Bluetooth 3.0/Bluetooth 5.0 3. Windows® 7 or later, Android 3.2 and above: Mac OS 10.5 or later. Note: Multimedia functions are partially invalid in different OS versions.

## TECHNICAL SPECIFICATIONS

- Connectivity: 2.4GHz/Bluetooth 3.0/Bluetooth 5.0
- Working distance: 2.4GHz about 20m/Bluetooth about 10m Power supply: 2\*AAA battery
- Interface: USB wireless receive
- Keyboard size: 394x145x23mm
  Rating: 3V == 2.5mA

### TROUBLESHOOTING

- 1. Make sure that the USB wireless receiver of the product is correctly plugged into the USB port of the computer.
- Make sure the computer meets the minimum system requirement.
  If the distance between the product and the receiver exceeds an effective range, please.
- reduce the distance for better performance. Windows is a trademark of the Microsoft Corporation in the United States and other
- Mac and MacOS are trademarks of Apple Inc., registered in the U.S. and other
- The Bluetooth® word mark and logos are registered trademarks owned by Bluetooth
- SIG. Inc. and any use of such marks by Officeworks Ltd is under license.
- Android is a trademark of Google LLC. IOS is a trademark or registered trademark of Cisco in the U.S. and other countries and

NOTE: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates uses and can radiate radio frequency energy and, if not installed and used in accordance with the instruction s,may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- -Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- -Consult the dealer or an experienced radio/TV technician for help
- Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.
- This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:
- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that

undesired operation

Risk of fire or explosion if the battery is replaced by an incorrecttype

回覧を Waltonbd.com

Product of WALTON