






Date: 31.OCT.2024 19:21:18

n77(3450-3550) SCS=30kHz DFT_256QAM BW=50MHz
LowChannel=631668 RB=1@0




Date: 31.OCT.2024 19:21:49

n77(3450-3550) SCS=30kHz DFT_256QAM BW=50MHz
LowChannel=631668 RB=128@0




Date: 31.OCT.2024 19:22:22

n77(3450-3550) SCS=30kHz CP_QPSK BW=50MHz
LowChannel=631668 RB=133@0




Date: 31.OCT.2024 19:22:59

n77(3450-3550) SCS=30kHz DFT_BPSK BW=50MHz
HighChannel=635000 RB=1@132




Date: 31.OCT.2024 19:23:31

n77(3450-3550) SCS=30kHz DFT_BPSK BW=50MHz
HighChannel=635000 RB=128@0




Date: 31.OCT.2024 19:24:03

n77(3450-3550) SCS=30kHz DFT_QPSK BW=50MHz
HighChannel=635000 RB=1@132




Date: 31.OCT.2024 19:24:35

n77(3450-3550) SCS=30kHz DFT_QPSK BW=50MHz
HighChannel=635000 RB=128@0




Date: 31.OCT.2024 19:25:07

n77(3450-3550) SCS=30kHz DFT_16QAM BW=50MHz
HighChannel=635000 RB=1@132




Date: 31.OCT.2024 19:25:38

n77(3450-3550) SCS=30kHz DFT_16QAM BW=50MHz
HighChannel=635000 RB=128@0




Date: 31.OCT.2024 19:26:10

n77(3450-3550) SCS=30kHz DFT_64QAM BW=50MHz
HighChannel=635000 RB=1@132




Date: 31.OCT.2024 19:26:42

n77(3450-3550) SCS=30kHz DFT_64QAM BW=50MHz
HighChannel=635000 RB=128@0




Date: 31.OCT.2024 19:27:15


n77(3450-3550) SCS=30kHz DFT_256QAM BW=50MHz
HighChannel=635000 RB=1@132




n77(3450-3550) SCS=30kHz DFT_256QAM BW=50MHz
HighChannel=635000 RB=128@0




n77(3450-3550) SCS=30kHz CP_QPSK BW=50MHz
HighChannel=635000 RB=133@0




n77(3450-3550) SCS=30kHz DFT_BPSK BW=60MHz
LowChannel=632000 RB=1@0




n77(3450-3550) SCS=30kHz DFT_BPSK BW=60MHz
LowChannel=632000 RB=162@0



n77(3450-3550) SCS=30kHz DFT_QPSK BW=60MHz
LowChannel=632000 RB=1@0




n77(3450-3550) SCS=30kHz DFT_QPSK BW=60MHz
LowChannel=632000 RB=162@0




Date: 31.OCT.2024 19:31:24

n77(3450-3550) SCS=30kHz DFT_16QAM BW=60MHz
LowChannel=632000 RB=1@0




Date: 31.OCT.2024 19:32:00

n77(3450-3550) SCS=30kHz DFT_16QAM BW=60MHz
LowChannel=632000 RB=162@0




Date: 31.OCT.2024 19:32:36

n77(3450-3550) SCS=30kHz DFT_64QAM BW=60MHz
LowChannel=632000 RB=1@0




Date: 31.OCT.2024 19:33:12

n77(3450-3550) SCS=30kHz DFT_64QAM BW=60MHz
LowChannel=632000 RB=162@0




Date: 31.OCT.2024 19:33:49

n77(3450-3550) SCS=30kHz DFT_256QAM BW=60MHz
LowChannel=632000 RB=1@0




Date: 31.OCT.2024 19:34:25

n77(3450-3550) SCS=30kHz DFT_256QAM BW=60MHz
LowChannel=632000 RB=162@0




Date: 31.OCT.2024 19:35:02

n77(3450-3550) SCS=30kHz CP_QPSK BW=60MHz
LowChannel=632000 RB=162@0




Date: 31.OCT.2024 19:35:58

n77(3450-3550) SCS=30kHz DFT_BPSK BW=60MHz
HighChannel=634666 RB=1@161




Date: 31.OCT.2024 19:36:34

n77(3450-3550) SCS=30kHz DFT_BPSK BW=60MHz
HighChannel=634666 RB=162@0




Date: 31.OCT.2024 19:37:11

n77(3450-3550) SCS=30kHz DFT_QPSK BW=60MHz
HighChannel=634666 RB=1@161




Date: 31.OCT.2024 19:37:47

n77(3450-3550) SCS=30kHz DFT_QPSK BW=60MHz
HighChannel=634666 RB=162@0




Date: 31.OCT.2024 19:38:23


n77(3450-3550) SCS=30kHz DFT_16QAM BW=60MHz
HighChannel=634666 RB=1@161




n77(3450-3550) SCS=30kHz DFT_16QAM BW=60MHz
HighChannel=634666 RB=162@0




n77(3450-3550) SCS=30kHz DFT_64QAM BW=60MHz
HighChannel=634666 RB=1@161




n77(3450-3550) SCS=30kHz DFT_64QAM BW=60MHz
HighChannel=634666 RB=162@0




n77(3450-3550) SCS=30kHz DFT_256QAM BW=60MHz
HighChannel=634666 RB=1@161



n77(3450-3550) SCS=30kHz DFT_256QAM BW=60MHz
HighChannel=634666 RB=162@0




n77(3450-3550) SCS=30kHz CP_QPSK BW=60MHz
HighChannel=634666 RB=162@0




Date: 31.OCT.2024 19:42:19

n77(3450-3550) SCS=30kHz DFT_BPSK BW=70MHz
LowChannel=632334 RB=1@0




Date: 31.OCT.2024 19:43:30

n77(3450-3550) SCS=30kHz DFT_BPSK BW=70MHz
LowChannel=632334 RB=180@0




Date: 31.OCT.2024 19:44:12

n77(3450-3550) SCS=30kHz DFT_QPSK BW=70MHz
LowChannel=632334 RB=1@0




Date: 31.OCT.2024 19:44:53

n77(3450-3550) SCS=30kHz DFT_QPSK BW=70MHz
LowChannel=632334 RB=180@0




Date: 31.OCT.2024 19:45:34

n77(3450-3550) SCS=30kHz DFT_16QAM BW=70MHz
LowChannel=632334 RB=1@0




Date: 31.OCT.2024 19:46:15


n77(3450-3550) SCS=30kHz DFT_16QAM BW=70MHz
LowChannel=632334 RB=180@0




n77(3450-3550) SCS=30kHz DFT_64QAM BW=70MHz
LowChannel=632334 RB=1@0




n77(3450-3550) SCS=30kHz DFT_64QAM BW=70MHz
LowChannel=632334 RB=180@0




n77(3450-3550) SCS=30kHz DFT_256QAM BW=70MHz
LowChannel=632334 RB=1@0




n77(3450-3550) SCS=30kHz DFT_256QAM BW=70MHz
LowChannel=632334 RB=180@0




n77(3450-3550) SCS=30kHz CP_QPSK BW=70MHz
LowChannel=632334 RB=189@0




n77(3450-3550) SCS=30kHz DFT_BPSK BW=70MHz
HighChannel=634332 RB=1@188




n77(3450-3550) SCS=30kHz DFT_BPSK BW=70MHz
HighChannel=634332 RB=180@0




n77(3450-3550) SCS=30kHz DFT_QPSK BW=70MHz
HighChannel=634332 RB=1@188




n77(3450-3550) SCS=30kHz DFT_QPSK BW=70MHz
HighChannel=634332 RB=180@0




n77(3450-3550) SCS=30kHz DFT_16QAM BW=70MHz
HighChannel=634332 RB=1@188




n77(3450-3550) SCS=30kHz DFT_16QAM BW=70MHz
HighChannel=634332 RB=180@0




n77(3450-3550) SCS=30kHz DFT_64QAM BW=70MHz
HighChannel=634332 RB=1@188




n77(3450-3550) SCS=30kHz DFT_64QAM BW=70MHz
HighChannel=634332 RB=180@0




n77(3450-3550) SCS=30kHz DFT_256QAM BW=70MHz
HighChannel=634332 RB=1@188




n77(3450-3550) SCS=30kHz DFT_256QAM BW=70MHz
HighChannel=634332 RB=180@0




n77(3450-3550) SCS=30kHz CP_QPSK BW=70MHz
HighChannel=634332 RB=189@0




n77(3450-3550) SCS=30kHz DFT_BPSK BW=80MHz
LowChannel=632668 RB=1@0




n77(3450-3550) SCS=30kHz DFT_BPSK BW=80MHz
LowChannel=632668 RB=216@0




n77(3450-3550) SCS=30kHz DFT_QPSK BW=80MHz
LowChannel=632668 RB=1@0




n77(3450-3550) SCS=30kHz DFT_QPSK BW=80MHz
LowChannel=632668 RB=216@0




n77(3450-3550) SCS=30kHz DFT_16QAM BW=80MHz
LowChannel=632668 RB=1@0




n77(3450-3550) SCS=30kHz DFT_16QAM BW=80MHz
LowChannel=632668 RB=216@0



n77(3450-3550) SCS=30kHz DFT_64QAM BW=80MHz
LowChannel=632668 RB=1@0




n77(3450-3550) SCS=30kHz DFT_64QAM BW=80MHz
LowChannel=632668 RB=216@0




Date: 31.OCT.2024 20:04:36

n77(3450-3550) SCS=30kHz DFT_256QAM BW=80MHz
LowChannel=632668 RB=1@0




Date: 31.OCT.2024 20:05:23

n77(3450-3550) SCS=30kHz DFT_256QAM BW=80MHz
LowChannel=632668 RB=216@0




Date: 31.OCT.2024 20:06:11

n77(3450-3550) SCS=30kHz CP_QPSK BW=80MHz
LowChannel=632668 RB=217@0




Date: 31.OCT.2024 20:07:03

n77(3450-3550) SCS=30kHz DFT_BPSK BW=80MHz
HighChannel=634000 RB=1@216




Date: 31.OCT.2024 20:07:50

n77(3450-3550) SCS=30kHz DFT_BPSK BW=80MHz
HighChannel=634000 RB=216@0




Date: 31.OCT.2024 20:08:37


n77(3450-3550) SCS=30kHz DFT_QPSK BW=80MHz
HighChannel=634000 RB=1@216




n77(3450-3550) SCS=30kHz DFT_QPSK BW=80MHz
HighChannel=634000 RB=216@0




n77(3450-3550) SCS=30kHz DFT_16QAM BW=80MHz
HighChannel=634000 RB=1@216




n77(3450-3550) SCS=30kHz DFT_16QAM BW=80MHz
HighChannel=634000 RB=216@0



n77(3450-3550) SCS=30kHz DFT_64QAM BW=80MHz
HighChannel=634000 RB=1@216



n77(3450-3550) SCS=30kHz DFT_64QAM BW=80MHz
HighChannel=634000 RB=216@0



n77(3450-3550) SCS=30kHz DFT_256QAM BW=80MHz
HighChannel=634000 RB=1@216