

Page 53 of 64 Report No.: EED32Q81469701



View of Product-09



View of Product-10















Report No.: EED32Q81469701 Page 54 of 64



View of Product-11



View of Product-12













Report No.: EED32Q81469701 Page 55 of 64



View of Product-13



View of Product-14


















View of Product-15



View of Product-16


















View of Product-17



View of Product-18














Report No.: EED32Q81469701 Page 58 of 64



View of Product-19



View of Product-20



















View of Product-21



View of Product-22



















View of Product-23



View of Product-24















Report No.: EED32Q81469701 Page 61 of 64



View of Product-25



View of Product-26















Report No.: EED32Q81469701 Page 62 of 64



View of Product-27



View of Product-28














Report No.: EED32Q81469701 Page 63 of 64



View of Product-29



View of Product-30

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.

\*\*\* End of Report \*\*\*