





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 286 of 708


802.11ax(HEW20)_HCH_6515MHz_RU52-MIMO_NTNV




802.11ax(HEW20)_HCH_6515MHz_RU106-Ant4_NTNV



802.11ax(HEW20)_HCH_6515MHz_RU106-Ant5_NTNV




802.11ax(HEW20)_HCH_6515MHz_RU106-MIMO_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 288 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 289 of 708







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 290 of 708

802.11ax(HEW40)_LCH_6445MHz_SU_/_Ant5_NTNV



802.11ax(HEW40)_LCH_6445MHz_SU_/_MIMO_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 291 of 708

802.11ax(HEW40)_MCH_6485MHz_SU_/_Ant4_NTNV




802.11ax(HEW40)_MCH_6485MHz_SU_/_Ant5_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 292 of 708







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 293 of 708

802.11ax(HEW80)_LCH_6465MHz_SU_/_Ant5_NTNV



802.11ax(HEW80)_LCH_6465MHz_SU_/_MIMO_NTNV






SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 294 of 708


4.2.5 PSD





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 295 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 296 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 297 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 298 of 708







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 299 of 708

802.11ax(HEW20)_LCH_6535MHz_RU26-Ant5_NTNV



802.11ax(HEW20)_LCH_6535MHz_RU26-MIMO_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 300 of 708


802.11ax(HEW20)_LCH_6535MHz_RU52-Ant4_NTNV




802.11ax(HEW20)_LCH_6535MHz_RU52-Ant5_NTNV




802.11ax(HEW20)_LCH_6535MHz_RU52-MIMO_NTNV




802.11ax(HEW20)_LCH_6535MHz_RU106-Ant4_NTNV



802.11ax(HEW20)_LCH_6535MHz_RU106-Ant5_NTNV




802.11ax(HEW20)_LCH_6535MHz_RU106-MIMO_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 303 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 304 of 708







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 305 of 708

802.11ax(HEW20)_MCH_6695MHz_RU26-Ant5_NTNV



802.11ax(HEW20)_MCH_6695MHz_RU26-MIMO_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 306 of 708

802.11ax(HEW20)_MCH_6695MHz_RU52-Ant4_NTNV




802.11ax(HEW20)_MCH_6695MHz_RU52-Ant5_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 307 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 308 of 708







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 309 of 708

802.11ax(HEW20)_MCH_6695MHz_SU_ / Ant4_NTNV




802.11ax(HEW20)_MCH_6695MHz_SU_ / Ant5_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 310 of 708







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 311 of 708

802.11ax(HEW20)_HCH_6855MHz_RU26-Ant5_NTNV



802.11ax(HEW20)_HCH_6855MHz_RU26-MIMO_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 312 of 708

802.11ax(HEW20)_HCH_6855MHz_RU52-Ant4_NTNV



802.11ax(HEW20)_HCH_6855MHz_RU52-Ant5_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 313 of 708

802.11ax(HEW20)_HCH_6855MHz_RU52-MIMO_NTNV




802.11ax(HEW20)_HCH_6855MHz_RU106-Ant4_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 314 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 315 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 316 of 708






SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207


Rev.: 02

Page: 317 of 708

802.11ax(HEW40)_LCH_6565MHz_SU_/_Ant5_NTNV



802.11ax(HEW40)_LCH_6565MHz_SU_/_MIMO_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 318 of 708

802.11ax(HEW40)_MCH_6685MHz_SU_/_Ant4_NTNV




802.11ax(HEW40)_MCH_6685MHz_SU_/_Ant5_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 319 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 320 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 321 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 322 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 323 of 708






SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 324 of 708



802.11ax(HEW80)_HCH_6785MHz_SU_/_MIMO_NTNV




802.11ax(HEW160)_MCH_6665MHz_SU_/_Ant4_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 326 of 708






SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 327 of 708


4.2.6 E.I.R.PSD





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 328 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 329 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 330 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 331 of 708







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 332 of 708

802.11ax(HEW20)_LCH_6535MHz_RU26-Ant5_NTNV



802.11ax(HEW20)_LCH_6535MHz_RU26-MIMO_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 333 of 708

802.11ax(HEW20)_LCH_6535MHz_RU52-Ant4_NTNV



802.11ax(HEW20)_LCH_6535MHz_RU52-Ant5_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 334 of 708

802.11ax(HEW20)_LCH_6535MHz_RU52-MIMO_NTNV



802.11ax(HEW20)_LCH_6535MHz_RU106-Ant4_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 335 of 708

802.11ax(HEW20)_LCH_6535MHz_RU106-Ant5_NTNV



802.11ax(HEW20)_LCH_6535MHz_RU106-MIMO_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 336 of 708

802.11ax(HEW20)_LCH_6535MHz_SU_/_Ant4_NTNV




802.11ax(HEW20)_LCH_6535MHz_SU_/_Ant5_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 337 of 708







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 338 of 708

802.11ax(HEW20)_MCH_6695MHz_RU26-Ant5_NTNV



802.11ax(HEW20)_MCH_6695MHz_RU26-MIMO_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 339 of 708

802.11ax(HEW20)_MCH_6695MHz_RU52-Ant4_NTNV



802.11ax(HEW20)_MCH_6695MHz_RU52-Ant5_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 340 of 708

802.11ax(HEW20)_MCH_6695MHz_RU52-MIMO_NTNV




802.11ax(HEW20)_MCH_6695MHz_RU106-Ant4_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 341 of 708







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 342 of 708

802.11ax(HEW20)_MCH_6695MHz_SU_ / Ant4_NTNV




802.11ax(HEW20)_MCH_6695MHz_SU_ / Ant5_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 343 of 708







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 344 of 708

802.11ax(HEW20)_HCH_6855MHz_RU26-Ant5_NTNV



802.11ax(HEW20)_HCH_6855MHz_RU26-MIMO_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 345 of 708

802.11ax(HEW20)_HCH_6855MHz_RU52-Ant4_NTNV



802.11ax(HEW20)_HCH_6855MHz_RU52-Ant5_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 346 of 708

802.11ax(HEW20)_HCH_6855MHz_RU52-MIMO_NTNV




802.11ax(HEW20)_HCH_6855MHz_RU106-Ant4_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 347 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 348 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 349 of 708







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 350 of 708

802.11ax(HEW40)_LCH_6565MHz_SU_/_Ant5_NTNV




802.11ax(HEW40)_LCH_6565MHz_SU_/_MIMO_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 351 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 352 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 353 of 708






SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 354 of 708



802.11ax(HEW80)_LCH_6625MHz_SU_ / MIMO_NTNV




802.11ax(HEW80)_MCH_6705MHz_SU_ / Ant4_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 356 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 357 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 358 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 359 of 708






SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 360 of 708


4.2.7 PSD





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 361 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 362 of 708







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 363 of 708

802.11a_HCH_7115MHz_Ant4_NTNV




802.11a_HCH_7115MHz_Ant5_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 364 of 708







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 365 of 708

802.11ax(HEW20)_LCH_6895MHz_RU26-Ant5_NTNV



802.11ax(HEW20)_LCH_6895MHz_RU26-MIMO_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 366 of 708

802.11ax(HEW20)_LCH_6895MHz_RU52-Ant4_NTNV




802.11ax(HEW20)_LCH_6895MHz_RU52-Ant5_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 367 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 368 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 369 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 370 of 708







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 371 of 708

802.11ax(HEW20)_MCH_6995MHz_RU26-Ant5_NTNV



802.11ax(HEW20)_MCH_6995MHz_RU26-MIMO_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 372 of 708

802.11ax(HEW20)_MCH_6995MHz_RU52-Ant4_NTNV




802.11ax(HEW20)_MCH_6995MHz_RU52-Ant5_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 373 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 374 of 708







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 375 of 708

802.11ax(HEW20)_MCH_6995MHz_SU_ / Ant4_NTNV




802.11ax(HEW20)_MCH_6995MHz_SU_ / Ant5_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 376 of 708







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 377 of 708

802.11ax(HEW20)_HCH_7115MHz_RU26-Ant5_NTNV



802.11ax(HEW20)_HCH_7115MHz_RU26-MIMO_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 378 of 708

802.11ax(HEW20)_HCH_7115MHz_RU52-Ant4_NTNV



802.11ax(HEW20)_HCH_7115MHz_RU52-Ant5_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 379 of 708

802.11ax(HEW20)_HCH_7115MHz_RU52-MIMO_NTNV



802.11ax(HEW20)_HCH_7115MHz_RU106-Ant4_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 380 of 708

802.11ax(HEW20)_HCH_7115MHz_RU106-Ant5_NTNV




802.11ax(HEW20)_HCH_7115MHz_RU106-MIMO_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 381 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 382 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 383 of 708







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 384 of 708

802.11ax(HEW40)_MCH_7005MHz_SU_/_Ant4_NTNV




802.11ax(HEW40)_MCH_7005MHz_SU_/_Ant5_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 385 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 386 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 387 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 388 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 389 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 390 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 391 of 708






SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 392 of 708


4.2.8 E.I.R.PSD





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 393 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 394 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 395 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 396 of 708







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 397 of 708

802.11ax(HEW20)_LCH_6895MHz_RU26-Ant5_NTNV



802.11ax(HEW20)_LCH_6895MHz_RU26-MIMO_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 398 of 708

802.11ax(HEW20)_LCH_6895MHz_RU52-Ant4_NTNV



802.11ax(HEW20)_LCH_6895MHz_RU52-Ant5_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 399 of 708


802.11ax(HEW20)_LCH_6895MHz_RU52-MIMO_NTNV




802.11ax(HEW20)_LCH_6895MHz_RU106-Ant4_NTNV



802.11ax(HEW20)_LCH_6895MHz_RU106-Ant5_NTNV



802.11ax(HEW20)_LCH_6895MHz_RU106-MIMO_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 401 of 708

802.11ax(HEW20)_LCH_6895MHz_SU_/_Ant4_NTNV




802.11ax(HEW20)_LCH_6895MHz_SU_/_Ant5_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 402 of 708







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 403 of 708

802.11ax(HEW20)_MCH_6995MHz_RU26-Ant5_NTNV



802.11ax(HEW20)_MCH_6995MHz_RU26-MIMO_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 404 of 708

802.11ax(HEW20)_MCH_6995MHz_RU52-Ant4_NTNV




802.11ax(HEW20)_MCH_6995MHz_RU52-Ant5_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 405 of 708







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 406 of 708

802.11ax(HEW20)_MCH_6995MHz_RU106-Ant5_NTNV



802.11ax(HEW20)_MCH_6995MHz_RU106-MIMO_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 407 of 708

802.11ax(HEW20)_MCH_6995MHz_SU_ / _Ant4_NTNV




802.11ax(HEW20)_MCH_6995MHz_SU_ / _Ant5_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 408 of 708






SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207


Rev.: 02

Page: 409 of 708

802.11ax(HEW20)_HCH_7115MHz_RU26-Ant5_NTNV



802.11ax(HEW20)_HCH_7115MHz_RU26-MIMO_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 410 of 708

802.11ax(HEW20)_HCH_7115MHz_RU52-Ant4_NTNV



802.11ax(HEW20)_HCH_7115MHz_RU52-Ant5_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 411 of 708

802.11ax(HEW20)_HCH_7115MHz_RU52-MIMO_NTNV




802.11ax(HEW20)_HCH_7115MHz_RU106-Ant4_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 412 of 708







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 413 of 708

802.11ax(HEW20)_HCH_7115MHz_SU_ / Ant4_NTNV




802.11ax(HEW20)_HCH_7115MHz_SU_ / Ant5_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 414 of 708







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 415 of 708

802.11ax(HEW40)_LCH_6925MHz_SU_/_Ant5_NTNV




802.11ax(HEW40)_LCH_6925MHz_SU_/_MIMO_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.


Report No.: SUCR250400034207
Rev.: 02
Page: 416 of 708





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 417 of 708







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 418 of 708

802.11ax(HEW40)_HCH_7085MHz_SU_/_Ant5_NTNV



802.11ax(HEW40)_HCH_7085MHz_SU_/_MIMO_NTNV







SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 419 of 708

802.11ax(HEW80)_LCH_6945MHz_SU_/_Ant4_NTNV



802.11ax(HEW80)_LCH_6945MHz_SU_/_Ant5_NTNV





SGS-CSTC Standards Technical Services (Suzhou) Co., Ltd.

Report No.: SUCR250400034207
Rev.: 02
Page: 420 of 708

