

Appendix Test Data


Report No.:	1812C50322812501	Test Sample No.:	1-2-2
Start Test Date:	2025-6-30	Finish Test Date:	2025-7-8
Test Engineer:	Hu Sen Guan	Auditor:	Justin Feng
Temperature:	27.0°C	Relative Humidity:	47%
Pressure:	101kPa		

Appendix A: 20dB Bandwidth

Test Result

Test Mode	Antenna	Frequency [MHz]	20db EBW[MHz]	FL[MHz]	FH[MHz]	Limit[MHz]	Verdict
DH5	Ant1	2402	0.96	2401.49	2402.45	---	---
DH5	Ant1	2441	1.02	2440.45	2441.47	---	---
DH5	Ant1	2480	1.00	2479.45	2480.45	---	---
2DH5	Ant1	2402	1.34	2401.29	2402.64	---	---
2DH5	Ant1	2441	1.34	2440.29	2441.64	---	---
2DH5	Ant1	2480	1.33	2479.30	2480.62	---	---
3DH5	Ant1	2402	1.31	2401.30	2402.61	---	---
3DH5	Ant1	2441	1.38	2440.27	2441.65	---	---
3DH5	Ant1	2480	1.34	2479.29	2480.62	---	---


Test Graphs





Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com









Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Appendix B: 99% Occupied Bandwidth

Test Result

Test Mode	Antenna	Frequency [MHz]	OCB [MHz]	FL[MHz]	FH[MHz]	Limit[MHz]	Verdict
DH5	Ant1	2402	0.87812	2401.5145	2402.3926	---	---
DH5	Ant1	2441	0.89311	2440.5115	2441.4046	---	---
DH5	Ant1	2480	0.87213	2479.5145	2480.3866	---	---
2DH5	Ant1	2402	1.2408	2401.3437	2402.5844	---	---
2DH5	Ant1	2441	1.2587	2440.3347	2441.5934	---	---
2DH5	Ant1	2480	1.2348	2479.3437	2480.5784	---	---
3DH5	Ant1	2402	1.2498	2401.3287	2402.5784	---	---
3DH5	Ant1	2441	1.2378	2440.3317	2441.5694	---	---
3DH5	Ant1	2480	1.2198	2479.3437	2480.5634	---	---


Test Graphs





Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com









Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com


Appendix C: Maximum Conducted Output Power


Test Result Peak


Test Mode	Antenna	Frequency[MHz]	Conducted Peak Power[dBm]	Conducted Limit[dBm]	Verdict
DH5	Ant1	2402	4.59	≤20.97	PASS
DH5	Ant1	2441	4.51	≤20.97	PASS
DH5	Ant1	2480	4.15	≤20.97	PASS
2DH5	Ant1	2402	4.83	≤20.97	PASS
2DH5	Ant1	2441	4.89	≤20.97	PASS
2DH5	Ant1	2480	4.37	≤20.97	PASS
3DH5	Ant1	2402	5.20	≤20.97	PASS
3DH5	Ant1	2441	4.75	≤20.97	PASS
3DH5	Ant1	2480	4.22	≤20.97	PASS


Test Graphs











Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com


Appendix D: Carrier frequency separation

Test Result

Test Mode	Antenna	Frequency [MHz]	Result [MHz]	Limit[MHz]	Verdict
DH5	Ant1	Hop	1.004	≥ 0.680	PASS
2DH5	Ant1	Hop	1.004	≥ 0.893	PASS
3DH5	Ant1	Hop	1.004	≥ 0.920	PASS

Test Graphs





Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com


Appendix E: Dwell Time

Test Result

Test Mode	Antenna	Frequency [MHz]	Burst Width [ms]	Total Hops [Num]	Result [s]	Limit [s]	Verdict
DH5	Ant1	Hop	2.885	104	0.3	≤0.4	PASS
2DH5	Ant1	Hop	2.892	127	0.367	≤0.4	PASS
3DH5	Ant1	Hop	2.893	100	0.289	≤0.4	PASS

Test Graphs






Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Appendix F: Number of Hopping Channel

Test Result

Test Mode	Antenna	Frequency [MHz]	Result [Num]	Limit [Num]	Verdict
DH5	Ant1	Hop	79	≥15	PASS
2DH5	Ant1	Hop	79	≥15	PASS
3DH5	Ant1	Hop	79	≥15	PASS


Test Graphs



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com


Appendix G: Conducted Band edge


Test Result


Test Mode	Antenna	Ch. Name	Frequency [MHz]	Ref. Level [dBm]	Result [dBm]	Limit [dBm]	Verdict
DH5	Ant1	Low	2402	4.45	-51.41	≤-15.55	PASS
DH5	Ant1	High	2480	3.81	-48.83	≤-16.19	PASS
DH5	Ant1	Low	Hop_2402	4.46	-53.25	≤-15.54	PASS
DH5	Ant1	High	Hop_2480	3.56	-50.26	≤-16.44	PASS
2DH5	Ant1	Low	2402	4.57	-42.73	≤-15.43	PASS
2DH5	Ant1	High	2480	3.62	-53.85	≤-16.38	PASS
2DH5	Ant1	Low	Hop_2402	0.44	-48.36	≤-19.56	PASS
2DH5	Ant1	High	Hop_2480	0.80	-46.91	≤-19.2	PASS
3DH5	Ant1	Low	2402	4.43	-44.37	≤-15.57	PASS
3DH5	Ant1	High	2480	3.95	-49.6	≤-16.05	PASS
3DH5	Ant1	Low	Hop_2402	1.21	-47.13	≤-18.79	PASS
3DH5	Ant1	High	Hop_2480	0.81	-52.74	≤-19.19	PASS


Remark:1. Regarding the spurious emissions from 30MHz to 26.5GHz, the cable lose have been set in the 'offset' of the Spectrum Analyzer during the test.


Test Graphs












Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Appendix H: Conducted Spurious Emission


Test Result


Test Mode	Antenna	Frequency[MHz]	Freq. Range [MHz]	Ref. Level [dBm]	Result [dBm]	Limit [dBm]	Verdict
DH5	Ant1	2402	0~Reference	4.22	4.22	---	PASS
DH5	Ant1	2402	30~1000	4.22	-68.07	≤-15.78	PASS
DH5	Ant1	2402	1000~26500	4.22	-40.65	≤-15.78	PASS
DH5	Ant1	2441	0~Reference	3.97	3.97	---	PASS
DH5	Ant1	2441	30~1000	3.97	-66.88	≤-16.03	PASS
DH5	Ant1	2441	1000~26500	3.97	-37.33	≤-16.03	PASS
DH5	Ant1	2480	0~Reference	3.52	3.52	---	PASS
DH5	Ant1	2480	30~1000	3.52	-67.46	≤-16.48	PASS
DH5	Ant1	2480	1000~26500	3.52	-40.08	≤-16.48	PASS
2DH5	Ant1	2402	0~Reference	4.53	4.53	---	PASS
2DH5	Ant1	2402	30~1000	4.53	-66.94	≤-15.47	PASS
2DH5	Ant1	2402	1000~26500	4.53	-42.72	≤-15.47	PASS
2DH5	Ant1	2441	0~Reference	4.23	4.23	---	PASS
2DH5	Ant1	2441	30~1000	4.23	-68.16	≤-15.77	PASS
2DH5	Ant1	2441	1000~26500	4.23	-37.75	≤-15.77	PASS
2DH5	Ant1	2480	0~Reference	1.15	1.15	---	PASS
2DH5	Ant1	2480	30~1000	1.15	-68.59	≤-18.85	PASS
2DH5	Ant1	2480	1000~26500	1.15	-40.48	≤-18.85	PASS
3DH5	Ant1	2402	0~Reference	4.22	4.22	---	PASS
3DH5	Ant1	2402	30~1000	4.22	-66.95	≤-15.78	PASS
3DH5	Ant1	2402	1000~26500	4.22	-41.47	≤-15.78	PASS
3DH5	Ant1	2441	0~Reference	4.04	4.04	---	PASS
3DH5	Ant1	2441	30~1000	4.04	-68.21	≤-15.96	PASS
3DH5	Ant1	2441	1000~26500	4.04	-39.97	≤-15.96	PASS
3DH5	Ant1	2480	0~Reference	3.91	3.91	---	PASS
3DH5	Ant1	2480	30~1000	3.91	-67.85	≤-16.09	PASS
3DH5	Ant1	2480	1000~26500	3.91	-40.33	≤-16.09	PASS

Remark:Regarding the spurious emissions from 30MHz to 26.5GHz, the cable lose have been set in the 'TDF' of the Spectrum Analyzer during the test.

Test Graphs










Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com









2DH5-Ant1-2402-30~1000-PASS



2DH5-Ant1-2402-1000~26500-PASS



2DH5-Ant1-2441-0~Reference-PASS




2DH5-Ant1-2441-30~1000-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




2DH5-Ant1-2441-1000~26500-PASS



2DH5-Ant1-2480-0~Reference-PASS



2DH5-Ant1-2480-30~1000-PASS





2DH5-Ant1-2480-1000~26500-PASS

Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com






3DH5-Ant1-2402-1000~26500-PASS




3DH5-Ant1-2441-0~Reference-PASS




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com





Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com


Appendix I: Duty Cycle


Test Result


Test Mode	Antenna	Frequency[MHz]	ON Time [ms]	Period [ms]	Duty Cycle [%]	Duty Cycle Factor[dB]
DH5	Ant1	2402	2.89	3.76	76.86	1.14
DH5	Ant1	2441	2.89	3.75	77.07	1.13
DH5	Ant1	2480	2.89	3.75	77.07	1.13
2DH5	Ant1	2402	2.89	3.75	77.07	1.13
2DH5	Ant1	2441	2.89	3.75	77.07	1.13
2DH5	Ant1	2480	2.90	3.75	77.33	1.12
3DH5	Ant1	2402	2.89	3.75	77.07	1.13
3DH5	Ant1	2441	2.89	3.75	77.07	1.13
3DH5	Ant1	2480	2.90	3.75	77.33	1.12


Test Graphs











---End---