



Figure 1: E-Label Screenshot

Steps to access the Regulatory E-Label on the 39DL Plus are listed below.

1. Press [SETUP MENU].
2. In the menu, select REGULATORY.
3. Press [ENTER].
4. Scroll through the markings and notices using the up and down arrow keys.
5. Press [MEAS] to return to the measurement screen.