



Report No.: EED32Q80383701 Page 31 of 42

PHOTOGRAPHS OF EUT Constructional Details



View of Product-1



View of Product-2



















View of Product-3




View of Product-4





Report No.: EED32Q80383701 Page 33 of 42



View of Product-5




View of Product-6






Report No.: EED32Q80383701 Page 34 of 42



View of Product-7



View of Product-8



















View of Product-9




View of Product-10






Report No. : EED32Q80383701 Page 36 of 42



View of Product-11




View of Product-12






Report No. : EED32Q80383701 Page 37 of 42



View of Product-13




View of Product-14






Report No.: EED32Q80383701 Page 38 of 42



View of Product-15



View of Product-16















Page 39 of 42 Report No.: EED32Q80383701







View of Product-18















Page 40 of 42 Report No.: EED32Q80383701



View of Product-19



View of Product-20















Report No.: EED32Q80383701 Page 41 of 42



View of Product-21



View of Product-22














Report No. : EED32Q80383701 Page 42 of 42



View of Product-23

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.

